

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
2/11/2022	1741B Cliff Dawson Rd	Needs to be opened up		14264	3/2/2022

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'56.36782"-W83°26'52.52558"

Location: 1151 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 51 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'58.00900"-W83°26'51.65375"

Location: 1241 Meadow Lakes Dr. Watkinsville GA.

Ditch Footage: 146 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'59.41201" - W83°26'50.00046"

Location: 1200 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 506 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'0.77744"-W83°26'49.37246"

Location: 1220 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 215 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

Culvert

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'4.50208"-W83°26'45.13186"

Location: 1 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 613 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

Culvert

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'4.66835"-W83°26'45.56131"

Location: 2 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 0 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'5.05225"-W83°26'44.32392"

Location: 3 Cliff Dawson Rd. Watkinsville GA

Ditch Footage: 128 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'5.07283"-W83°26'42.68143"

Location: 4 Cliff Dawson Rd. Watkinson, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'5.70441"-W83°26'37.13742"

Location: 1401 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 533 ft.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

Culvert

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'5.25817"-W83°26'36.08707"

Location: 1447 Cliff Dawson Rd, Watkinsville GA.

Ditch Footage: 0 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

JB

CATCH BASIN INSPECTION CHECKLIST

Date: 2-11-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'5.07855"-W83°26'40.54300"Location: 1010 Moss Creek Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'10.32238"-W83°25'49.41295"

Location: 1761 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 242 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'11.03620"-W83°25'50.52870"

Location: 1761B Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 110 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'11.86487"-W83°25'51.89915"

Location: 1741 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 115 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'12.02096"-W83°25'53.52665"

Location: 1649 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 584 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'12.84305" - W83°25'54.82552"

Location: 1741B Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 243 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes/ <u>No</u>	
Vegetation maintained to capture sediment	Yes/ <u>No</u>	
Debris (litter, branches, brush, etc.)	Yes/ <u>No</u>	
Excessive siltation buildup	Yes/ <u>No</u>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes/ <u>No</u>	
Pipes/Cross Culverts (clogged or damaged)	<u>(Yes)</u> No	<u>Need to be opened up.</u>

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14264	Road Department	Michael Weathers		2/11/2022	7:30 AM
Location of Request					

1741B Cliff Dawson Rd

Task	Date Completed
Pipe Repair	3/2/2022

Action for Task	Date of Action
opened end of pipe	3/2/2022

Employee Hours and Cost	# of Employees	Combined Hours	Cost of Action
	4	2.00	

Subcontractor Hours and Cost

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	G489 FORD	0.50	
	G771	0.50	

Materials Cost

Employee Costs for this Task:	\$0.00
Subcontractor Costs for this Task:	\$0.00
Equipment Costs for this Task:	\$0.00
Materials Costs for this Task:	\$0.00

Total All Employee Costs:	\$0.00
Total All Subcontractor Costs:	\$0.00
Total All Equipment Costs:	\$0.00
Total All Materials Costs:	\$0.00
GRAND TOTAL:	\$0.00

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'13.06940"-W83°25'57.22964"

Location: 17616 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 176 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'12.94576"-W83°25'59.88387"

Location: 1669 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 192 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 2-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'12.86488"-W83°26'0.89569"

Location: 1661 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 61 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No	