

STORM SYSTEM SERVICES

Inspection Date 12/8/22 Job Number 6AQ-164-102 814

Job Name Markets at Epps Bridge

Job Address 1850 Epps Bridge Pkwy
Athens GA

Inspector's Name Tim Cooper

Grading Permit # _____ TCLP # _____

Lat: 33.91664 Long: 83.44359

Traffic	<input checked="" type="checkbox"/>
Hatch	<input type="checkbox"/>
Steel Lid	<input type="checkbox"/>
Size	<u>4x6 Baffle Box</u>
Time	<u>1/2</u>
Disposal Fee (Y/N)	<input checked="" type="checkbox"/>
Volume (Gal.)	<u>75</u>

Maintenance Cleaning Checklist

Water Level	Oil Bucket Level	Sediment Level	Trash Conditions
<input type="checkbox"/> low	<input type="checkbox"/> low	<input checked="" type="checkbox"/> little	<input checked="" type="checkbox"/> minimal
<input checked="" type="checkbox"/> normal	<input type="checkbox"/> typical <u>N/A</u>	<input type="checkbox"/> typical	<input type="checkbox"/> typical
<input type="checkbox"/> above outlet	<input type="checkbox"/> high	<input type="checkbox"/> excessive	<input type="checkbox"/> unacceptably high

Recommendations: This unit appears to need maintenance on a shorter longer unchanged schedule.

This report is a complete and accurate description of conditions found at the time of inspection and all work performed on this device

Inspector's Signature: Tim Cooper

Date: 12/8/22

Inspection Data

Sediment: inlet side	<u>1</u>	Inches
Sediment: outlet side	<u>1/2</u>	Inches

Water in unit at inspection	<u>2</u>	Inches
Fluid in bucket at inspection	<u>1/4</u>	Inches

Items Maintained

Comments

Lid: inspect bolts, eyehooks, hinges	<u>OK</u> <u>Cleaned & Maintained</u>
Trash Rack: inspect aluminum mesh	<u>N/A</u>
Baffle Plates: inspect for damage	<u>N/A</u>
Oil Bucket: Leaks / Sheen	<u>N/A</u>
Surroundings: check grass/plantings	<u>OK</u>
Coconut Fiber / Flapper	<u>N/A</u>