

Decor

Inspection Date 1-19-22 Job Number GAC-1104-102814

Job Name Markets @ Epps Bridge

Job Address 1850 Epps Bridge Pkwy
Athens, GA 30606

Inspector's Name Chris Kirk

Lat: 33,911064° Long: 083,44359°

Traffic	<input checked="" type="checkbox"/>
Hatch	<input type="checkbox"/>
Steel Lid	<input type="checkbox"/>
Size	<u>16' x 4'</u>
Time	<u>1/2</u>
Disposal Fee (Y/N)	<u>Y</u>
Volume (Gal.)	<u>50</u>

Maintenance Cleaning Checklist

Water Level	Oil Bucket Level	Sediment Level	Trash Conditions
<input type="checkbox"/> low	<input type="checkbox"/> low	<input checked="" type="checkbox"/> little	<input type="checkbox"/> minimal
<input checked="" type="checkbox"/> normal	<input type="checkbox"/> typical	<input type="checkbox"/> typical	<input type="checkbox"/> typical
<input type="checkbox"/> above outlet	<input type="checkbox"/> high	<input type="checkbox"/> excessive	<input type="checkbox"/> unacceptably high

Recommendations: This unit appears to need maintenance on a shorter longer unchanged schedule.

This report is a complete and accurate description of conditions found at the time of inspection and all work performed on this device

Inspector's Signature:

Date: 1-19-22

Inspection Data

Sediment: inlet side	2 1/2"	Inches	Water in unit at inspection	10"	Inches
Sediment: outlet side	6"	Inches	Fluid in bucket at inspection	2 1/2"	Inches

Items Maintained

Comments

Lid: inspect bolts, eyehooks, hinges	OK	Cleaned & maintained
Trash Rack: inspect aluminum mesh	N/A	
Baffle Plates: inspect for damage	N/A	
Oil Bucket: Leaks / Sheen	N/A	
Surroundings: check grass/plantings	OK	
Coconut Fiber / Flapper	N/A	

STORM SYSTEM SERVICES

Division of CRYSTALSTREAM TECHNOLOGIES

Deoncc

Inspection Date 1-19-22 Job Number GAO-253-121806

Job Name 1 Hop @ Epps Bridge

Job Address 1001 Parkway Place
Athens, GA

Inspector's Name Chris Kirk

Grading Permit # TCLP #

Lat: 33.92118 Long: 083.44251


Traffic	<input type="checkbox"/>
Hatch	<input checked="" type="checkbox"/>
Steel Lid	<input type="checkbox"/>
Size	<u>9 56</u>
Time	<u>2</u>
Disposal Fee (Y/N)	<u>Y</u>
Volume (Gal.)	<u>125</u>

Maintenance Cleaning Checklist

Water Level	Oil Bucket Level	Sediment Level	Trash Conditions
<input type="checkbox"/> low	<input type="checkbox"/> low	<input type="checkbox"/> little	<input type="checkbox"/> minimal
<input checked="" type="checkbox"/> normal	<input checked="" type="checkbox"/> typical	<input type="checkbox"/> typical	<input type="checkbox"/> typical
<input type="checkbox"/> above outlet	<input type="checkbox"/> high	<input type="checkbox"/> excessive	<input checked="" type="checkbox"/> unacceptably high

Recommendations: This unit appears to need maintenance on a shorter longer unchanged schedule.

This report is a complete and accurate description of conditions found at the time of inspection and all work performed on this device

Inspector's Signature: 

Date: 1-19-22

Inspection Data

Sediment: inlet side	<u>9 1/2 "</u> Inches	Water in unit at inspection	<u>45 "</u> Inches
Sediment: outlet side	<u>4 "</u> Inches	Fluid in bucket at inspection	<u>37 "</u> Inches

Items Maintained

Comments

Lid: inspect bolts, eyehooks, hinges	<u>OK</u>	- cleaned & maintained
Trash Rack: inspect aluminum mesh	<u>3/4 compacted</u>	- cleaned
Baffle Plates: inspect for damage	<u>Reinstalled</u>	
Oil Bucket: Leaks / Sheen	<u>OK - cleaned</u>	
Surroundings: check grass/plantings	<u>OK</u>	
Coconut Fiber / Flapper		<u>Coconut Replaced</u>