

Location & number of catch basin educational markers inspected during 2020 reporting period:

<u>Location</u>	<u>Markers Inspected</u>	<u>Number Replaced</u>
Fernwood	32	2 (to be replaced)
Planters Ridge	19	19 (to be added)
Total:	<u>51</u>	<u>21</u>

Two markers need to be replaced in Fernwood subdivision. Markers need to be added to all of the catch basins in Planters Ridge subdivision. The markers will be installed in 2021 as soon as the weather conditions are favorable for the adhesive to properly dry.

