

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
11/24/2021	1061 Oaklake Trail	Structure needs backfill on sides		13909	12/15/2021
	1030 Oaklake Circle	Need to fill out back of curb		13910	12/15/2021
	1010 Oaklake Circle	Needs to be regROUTed		13961	12/20/2021

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'43.84116"-W83°29'35.71772"Location: 1001-1009 Oak Lake Terr. in Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(2)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'42.15729"-W83°29'36.51578"Location: 1010 Oak Lake Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(3)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 54' 41, W 610" - W 83° 29' 33, 72851 "Location: 1011 Oaklake Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(4)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'37.76998"-W83°29'29.11756"Location: 1061 Oaklake Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	Structure needs backfill on sides
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13909	Road Department	Michael Weathers		12/15/2021	7:30 AM

Location of Request

1061 Oak Lake Trail

Task	Date Completed
Catch Basin Repair	12/15/2021

Action for Task	Date of Action
backfilled around structure	12/15/2021

Employee Hours and Cost	# of Employees	Combined Hours	Cost of Action
	4	4.00	

Subcontractor Hours and Cost

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	D146 FORD	1.00	
	D321 CAT EXCAVATOR	1.00	
	D494 DUMP TRUCK	1.00	
	G489 FORD	1.00	

Materials Cost	Material Name	Amount Used (Units)	Measured In	Material Cost
	Dirt	1.00	Ton	

Employee Costs for this Task:	\$0.00
Subcontractor Costs for this Task:	\$0.00
Equipment Costs for this Task:	\$0.00
Materials Costs for this Task:	\$0.00

Total All Employee Costs:	\$0.00
Total All Subcontractor Costs:	\$0.00
Total All Equipment Costs:	\$0.00
Total All Materials Costs:	\$0.00
GRAND TOTAL:	\$0.00

(5)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'37.24868" - W83°29'29.03219"Location: 1080 Oaklake Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

(6)

Date: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'35,61795" - W83°29'27.00665"Location: 1100 Oak Lake Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(7)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 54' 42.25036" - W 83° 29' 37.24389"Location: 1030 Oaklak Terr, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(8)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): Willian RhodesLocation/DescriptionGPS Point Name: N33°54'41.96032"-W83°29'37.01661"Location: 1011-1029 OakLink Terr, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(9)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'40.08054"-W83°29'38.21845"Location: 1031-1071 Oaklak Terr, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <u>No</u>	
"No dumping" educational marker	Yes / <u>No</u>	
Trash or debris at inlet opening	Yes / <u>No</u>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <u>No</u>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <u>No</u>	
Pipes (roots, damaged, flow impeded)	Yes / <u>No</u>	

(10)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 54' 40.36" W 83° 29' 38.50053"Location: 1030 Oaklake Ter, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

(11)

Date: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'36.23862" - W83°29'39.46702"Location: 1090 OakLake Terr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(12)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'35.79661"-W83°29'39.57001"Location: 1090 Oaklak Terro, Watkinsville GA,

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(13)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33°54'32.20552" - W 83°29'38.25346"Location: 1130 Oaklake Terr, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(14)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'31.75403" - W83°29'38.21301"Location: 1130 Oaklake Ter, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(15)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 54' 29.21935" - W 83° 29' 41.16093"Location: 1160 Oaklak Terr, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(16)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'29.09885"-W83°29'40.82964"Location: 1161 Oaklake Terr., Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(JB)

CATCH BASIN INSPECTION CHECKLISTDate: 11-21-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'26.28" W83°29'43.90"78"Location: 1191 Oaklake Terr, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(17)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'26.3/184"-W83°29'44.79214"Location: 1091 Oaklake Cir, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(18)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'24.16079" - W83°29'49.42106"Location: 1231 OakLake Terr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(19)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'24.47588"- W83°29'49.59041"Location: 1230 Oaklake Terr, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(20)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'25.97574"-W83°29'45.86720"Location: 1048-1098 Oak Lake Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(21)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'26, 16137"-W83°29'45.54135"Location: 1091 Oaklake Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

(22)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 54' 28.44760" - W 83° 29' 46.76250"Location: 1071 Oak Lake Cir, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(23)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'28.46460"-W83°29'47.09911"Location: 1080 OakLake Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

(24)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'34.49225" - W83°29'43.17841"Location: 1031 OakLake Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(25)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'34.80287"-W83°29'43.52272"Location: 1030 Oaklake Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	<i>Need to filled at back of curb.</i>
"No dumping" educational marker	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input type="radio"/> No <input checked="" type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13910	Road Department	Michael Weathers		12/15/2021	7:30 AM
Location of Request					
1030 Oak Lake Circle					
Task	Date Completed				
Catch Basin Repair	12/15/2021				
Action for Task	Date of Action				
backfilled around structure	12/15/2021				
<u>Employee Hours and Cost</u>	<u># of Employees</u>	<u>Combined Hours</u>	<u>Cost of Action</u>		
	4	4.00			
Subcontractor Hours and Cost					
<u>Equipment Hours and Cost</u>	<u>Equipment</u>	<u>Hours</u>	<u>Equip Cost</u>		
	D146 FORD	1.00			
	D321 CAT EXCAVATOR	1.00			
	D494 DUMP TRUCK	1.00			
	G489 FORD	1.00			
<u>Materials Cost</u>	<u>Material Name</u>	<u>Amount Used (Units)</u>	<u>Measured In</u>	<u>Material Cost</u>	
	Dirt	0.50	Ton		
Employee Costs for this Task:	\$0.00				
Subcontractor Costs for this Task:	\$0.00				
Equipment Costs for this Task:	\$0.00				
Materials Costs for this Task:	\$0.00				
Total All Employee Costs:	\$0.00				
Total All Subcontractor Costs:	\$0.00				
Total All Equipment Costs:	\$0.00				
Total All Materials Costs:	\$0.00				
GRAND TOTAL:	\$0.00				

(26)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'36.4" / W83°29'40.15565"Location: 1010 OakLake Cir., Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	Need to be regrouted
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13961	Road Department	Michael Weathers		12/20/2021	7:30 AM

Location of Request

1010 Oaklake Circle

Task

Catch Basin Repair

Date Completed

12/20/2021

Action for Task

fixed hole at back of catch basin

Date of Action

12/20/2021

<u>Employee Hours and Cost</u>	<u># of Employees</u>	<u>Combined Hours</u>	<u>Cost of Action</u>
--------------------------------	-----------------------	-----------------------	-----------------------

2	4.00
---	------

Subcontractor Hours and Cost

<u>Equipment Hours and Cost</u>	<u>Equipment</u>	<u>Hours</u>	<u>Equip Cost</u>
	G771	2.00	

<u>Materials Cost</u>	<u>Material Name</u>	<u>Amount Used (Units)</u>	<u>Measured In</u>	<u>Material Cost</u>
	Quickcrete	1.00	bags	

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

CATCH BASIN INSPECTION CHECKLIST

(27)

Date: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'36.03005"-W83°29'40.03197"Location: 1001-1047 OakLake Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'5.82367"-W83°32'6.40661"Location: 1012 Pleasant Hill Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'4.69153" - W83°32'6.39362"Location: 1030 Pleasant Hill Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William Rhodes**Location/Description**ID #: N33°55'2.65959"- W83°32'5.97649"Location: 1041 Pleasant Hill Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William Rhodes**Location/Description**ID #: N33°55'0.63135"-W83°32'6.34471"Location: 1061 Pleasant Hill Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'0.05840"-W83°32'6.61661"Location: 1081 Pleasant Hill Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Excessive siltation buildup	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William Rhodes**Location/Description**ID #: N33°54'57.95378"-W83°32'7.66890"Location: 1101 Pleasant Hill Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William Rhodes**Location/Description**ID #: N33°54'57.34" W83°32'8.60328"Location: 1110 Pleasant Hill Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William Rhodes**Location/Description**ID #: N 33° 54' 53.66941" - W 83° 32' 10.05626"Location: 1151 Pleasant Hill Dr, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionID #: N 33° 54' 51.84720" - W 83° 32' 10.93441"Location: 1171 Pleasant Hill Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'49.11879" - W83°32'13.69980"Location: 1201 Pleasant Hill Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'52.71332"-W83°32'12.25956"Location: 1010 Pleasant Ct.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'52.37" W83°32'12.88068"Location: 1180 Pleasant Hill Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(1)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'45.70223"-W83°34'5.88963"Location: 1030 Vanessa Ave, Bogart GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(2)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'45.80845" - W83°34'6.13692"Location: 1041 Vanessa Ave, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(3)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'46.46834"-W83°34'49.8644"Location: 1061 Vanessa Ave, Bogart GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(4)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'46.08270" - W83°34'4.86131"Location: 1060 Vanessa Ave., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

CATCH BASIN INSPECTION CHECKLIST

(5)

Date: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 53' 47.9682" - W 83° 34' 0.11908"Location: 1090 Vanessa Ave., Bogart, GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(JB1)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'47.84592" - W83°33'59.87573"Location: 1090 Vanessa Ave., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

(6)

Date: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'47.92594"-W83°33'58.73070Location: 1081 Vanessa Ave, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

CATCH BASIN INSPECTION CHECKLIST

(7)

Date: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'47.71957"-W83°33'58.55193"Location: 1010 Elyse Dr., Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(8)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'47.50516"-W83°33'58.76354"Location: 1090 Vanessa Ave., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(JB 2)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'47.66557"-W83°33'58.89778"Location: 1081 Vanessa Ave, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(JB3)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'47.22238"-W83°33'58.48122"Location: 1090 Vanessa Ave., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(JB 4)

CATCH BASIN INSPECTION CHECKLIST

Date: 11-24-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'46.81725"-W83°33'58.18112"

Location: 1120 Vanessa Ave., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

(9)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 53' 46.69691" - W 83° 33' 58.03442"Location: 1120 Vanessa Ave, Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

CATCH BASIN INSPECTION CHECKLIST

(10)

Date: 11-24-2021Inspector(s): Williams RhodesLocation/DescriptionGPS Point Name: N33°53'45.63164"-W83°33'58.01931"Location: 1120 Vanessa Ave, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(11)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 53' 42, 92316" - W 83° 34' 3, 80710"Location: 1040 Rebekah Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(12)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhoadsLocation/DescriptionGPS Point Name: N 33° 53' 43.11805" - W 83° 34' 3.36582"Location: 1031 Rebekah Dr., Bogart GA.

Inspection Items	Maintenace Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 53' 41.88470" - W 83° 34' 2.51105"Location: 1040 Rebekah Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'42.17013" - W83°34'2.22368"Location: 1040 Rebekah Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

(JB5)

CATCH BASIN INSPECTION CHECKLISTDate: 11-24-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'42.20034"-W83°34'2.10894"Location: 1031 Rebekah Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	