

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
12/6/2021	1111 Scarlet Oak Circle	Need to clean silt from structure	0.5	13882	12/14/2021
	1321 Scarlet Oak Circle	Need to clean silt from structure	0.5	13883	12/14/2021
	1320 Scarlet Oak Circle	Need to clean silt from structure	0.5	13884	12/14/2021
	1020 Lake Welbrook Dr	Need to clean silt from structure	3	13885	12/14/2021
	1140 Lake Welbrook Dr	Need to refill dirt at back of curb		13834	12/7/2021
		ASAP! Danger sinkhole developed			
	1260 Scarlett Oak Circle	Need to clean silt from structure	1	13886	12/14/2021
	1251 Scarlet Oak Circle	Need to clean silt from structure	0.5	13887	12/14/2021
	1301 Scarlet Oak Circle	Need to clean silt from structure	0.5	13888	12/14/2021
	1300 Scarlet Oak Circle	Need to clean silt from structure	1	13889	12/14/2021
	1020 Etowah Court	Need to clean silt from structure	6	13968	12/21/2021
		Need to reposition structure			

(CBG)

CATCH BASIN INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'50.38197"-W83°26'18.83404"Location: 1111 Scarlet Oak Cir., Athens, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="checkbox"/> No	
"No dumping" educational marker	Yes <input checked="" type="checkbox"/> No	
Trash or debris at inlet opening	Yes <input checked="" type="checkbox"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	<input checked="" type="checkbox"/> Yes / No	Need to clean silt from structure.
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="checkbox"/> No	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="checkbox"/> No	

CATCH BASIN INSPECTION CHECKLIST

(CB7)

Date: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'50.41390" - W83°26'18.92192"Location: 1111 Scarlet Oak Cir, Athens GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	<i>Need to remove silt from structure</i>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13882	Road Department	Michael Weathers		12/14/2021	7:30 AM
Location of Request					
1111 Scarlet Oak Circle					
Task	Date Completed				
Catch Basin Cleaning	12/14/2021				
Action for Task	Date of Action				
removed 1/2 ton of silt from structure	12/14/2021				
<u>Employee Hours and Cost</u>	# of Employees	Combined Hours	Cost of Action		
	6	3.00			
<u>Subcontractor Hours and Cost</u>					
<u>Equipment Hours and Cost</u>	Equipment	Hours	Equip Cost		
	D020 FORD CAB AND CHASSIS(Water)	0.50			
	D146 FORD	0.50			
	D321 CAT EXCAVATOR	0.50			
	D494 DUMP TRUCK	0.50			
	G489 FORD	0.50			
<u>Materials Cost</u>					
Employee Costs for this Task:	\$0.00				
Subcontractor Costs for this Task:	\$0.00				
Equipment Costs for this Task:	\$0.00				
Materials Costs for this Task:	\$0.00				
Total All Employee Costs:	\$0.00				
Total All Subcontractor Costs:	\$0.00				
Total All Equipment Costs:	\$0.00				
Total All Materials Costs:	\$0.00				
GRAND TOTAL:	\$0.00				

(GI 1)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 53' 56.03865" - W 83° 26' 18.30364"Location: 1321 Scarlet Oak Cir, Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(GI 2)

CATCH BASIN INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): W. William RhodesLocation/DescriptionGPS Point Name: N33°53'56.28" W83°26'18.58770"Location: 1070 Scarlet Oak Cir., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(CB10)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'57.61664"-W83°26'16.99626"

Location: 1030 Scarlet Oaks Cr., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

(CBII)

Date: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'57.15" W83°26'16.70899"Location: 1321 Scarlet Oak Cir, Athens, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	<i>Need to remove silt from structure.</i>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request																								
13883	Road Department	Michael Weathers		12/14/2021	7:30 AM																								
Location of Request																													
1321 Scarlet Oak Circle																													
Task	Date Completed																												
Catch Basin Cleaning	12/14/2021																												
Action for Task	Date of Action																												
removed 1/2 ton of silt from structure	12/14/2021																												
<table border="1"> <thead> <tr> <th><u>Employee Hours and Cost</u></th> <th><u># of Employees</u></th> <th><u>Combined Hours</u></th> <th><u>Cost of Action</u></th> </tr> </thead> <tbody> <tr> <td></td> <td>6</td> <td>3.00</td> <td></td> </tr> </tbody> </table>						<u>Employee Hours and Cost</u>	<u># of Employees</u>	<u>Combined Hours</u>	<u>Cost of Action</u>		6	3.00																	
<u>Employee Hours and Cost</u>	<u># of Employees</u>	<u>Combined Hours</u>	<u>Cost of Action</u>																										
	6	3.00																											
<u>Subcontractor Hours and Cost</u>																													
<table border="1"> <thead> <tr> <th><u>Equipment Hours and Cost</u></th> <th><u>Equipment</u></th> <th><u>Hours</u></th> <th><u>Equip Cost</u></th> </tr> </thead> <tbody> <tr> <td></td> <td>D020 FORD CAB AND CHASSIS(Water)</td> <td>0.50</td> <td></td> </tr> <tr> <td></td> <td>D146 FORD</td> <td>0.50</td> <td></td> </tr> <tr> <td></td> <td>D321 CAT EXCAVATOR</td> <td>0.50</td> <td></td> </tr> <tr> <td></td> <td>D494 DUMP TRUCK</td> <td>0.50</td> <td></td> </tr> <tr> <td></td> <td>G489 FORD</td> <td>0.50</td> <td></td> </tr> </tbody> </table>						<u>Equipment Hours and Cost</u>	<u>Equipment</u>	<u>Hours</u>	<u>Equip Cost</u>		D020 FORD CAB AND CHASSIS(Water)	0.50			D146 FORD	0.50			D321 CAT EXCAVATOR	0.50			D494 DUMP TRUCK	0.50			G489 FORD	0.50	
<u>Equipment Hours and Cost</u>	<u>Equipment</u>	<u>Hours</u>	<u>Equip Cost</u>																										
	D020 FORD CAB AND CHASSIS(Water)	0.50																											
	D146 FORD	0.50																											
	D321 CAT EXCAVATOR	0.50																											
	D494 DUMP TRUCK	0.50																											
	G489 FORD	0.50																											
<u>Materials Cost</u>																													
Employee Costs for this Task:	\$0.00																												
Subcontractor Costs for this Task:	\$0.00																												
Equipment Costs for this Task:	\$0.00																												
Materials Costs for this Task:	\$0.00																												
<table border="1"> <tr> <td>Total All Employee Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Subcontractor Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Equipment Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Materials Costs:</td> <td>\$0.00</td> </tr> <tr> <td>GRAND TOTAL:</td> <td>\$0.00</td> </tr> </table>						Total All Employee Costs:	\$0.00	Total All Subcontractor Costs:	\$0.00	Total All Equipment Costs:	\$0.00	Total All Materials Costs:	\$0.00	GRAND TOTAL:	\$0.00														
Total All Employee Costs:	\$0.00																												
Total All Subcontractor Costs:	\$0.00																												
Total All Equipment Costs:	\$0.00																												
Total All Materials Costs:	\$0.00																												
GRAND TOTAL:	\$0.00																												

CATCH BASIN INSPECTION CHECKLIST

(CB12)

Date: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'57.26020"-W83°26'16.33513"Location: 1320 Scarlet Oak Cir., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	<i>Need to remove silt from structure</i>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13884	Road Department	Michael Weathers		12/14/2021	7:30 AM
Location of Request					
1320 Scarlet Oak Circle					
Task	Date Completed				
Catch Basin Cleaning	12/14/2021				
Action for Task	Date of Action				
removed 1/2 ton of silt from structure	12/14/2021				
<u>Employee Hours and Cost</u>		# of Employees	Combined Hours	Cost of Action	
		6	3.00		
<u>Subcontractor Hours and Cost</u>					
<u>Equipment Hours and Cost</u>		Equipment	Hours	Equip Cost	
		D020 FORD CAB AND CHASSIS(Water)	0.50		
		D146 FORD	0.50		
		D321 CAT EXCAVATOR	0.50		
		D494 DUMP TRUCK	0.50		
		G489 FORD	0.50		
<u>Materials Cost</u>					
Employee Costs for this Task:	\$0.00				
Subcontractor Costs for this Task:	\$0.00				
Equipment Costs for this Task:	\$0.00				
Materials Costs for this Task:	\$0.00				
Total All Employee Costs:	\$0.00				
Total All Subcontractor Costs:	\$0.00				
Total All Equipment Costs:	\$0.00				
Total All Materials Costs:	\$0.00				
GRAND TOTAL:	\$0.00				

CATCH BASIN INSPECTION CHECKLIST

(CB13)

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'5.26964"-W83°26'17.99416"

Location: 1013 Lake Wilbrook Dr, Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(CB14)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33° 54' 8.17729" - W 83° 26' 18.83280"

Location: 1001 Lake Welbrook Dr., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(CB15)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33° 54' 5.22927" - W 83° 26' 18.40665"

Location: 1020 Lake Wolbrook Dr., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
"No dumping" educational marker	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Trash or debris at inlet opening	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Remove silt from structure
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13885	Road Department	Michael Weathers		12/14/2021	7:30 AM

Location of Request

1020 Lake Welbrook Drive

Task

Catch Basin Cleaning

Date Completed

12/14/2021

Action for Task

removed 3 tons of silt from structure

Date of Action

12/14/2021

Employee Hours and Cost
of Employees
Combined Hours
Cost of Action

6

3.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

D020 FORD CAB AND CHASSIS(Water)	0.50
D146 FORD	0.50
D321 CAT EXCAVATOR	0.50
D494 DUMP TRUCK	0.50
G489 FORD	0.50

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

(CB16)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'58.9/309"-W83°26'12.19359"

Location: 1120 Lake Wilbrook Dr., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

(CB17)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'59.10661"-W83°26'12.00366"

Location: 1121 Lake Wolbrook Dr., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

(GI3)

Date: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'57.19791" - W83°26'11.19060"Location: 1140 Lake Welbrook Dr., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	<input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No	Need to refill dirt at back of curb ASAP! Danger sinkhole developed.
"No dumping" educational marker	<input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No	
Trash or debris at inlet opening	<input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	<input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	<input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No	
Pipes (roots, damaged, flow impeded)	<input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No	

Work Request Invoice - Public Works

WOID Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13834 Road Department	Michael Weathers		12/7/2021	7:30 AM

Location of Request

1140 Lake Wellbrook Drive

Task

Catch Basin Repair

Date Completed

12/7/2021

Date of Action

12/7/2021

Action for Task

filled in sinkhole with concrete

<u>Employee Hours and Cost</u>	<u># of Employees</u>	<u>Combined Hours</u>	<u>Cost of Action</u>
	4	16.00	

Subcontractor Hours and Cost

<u>Equipment Hours and Cost</u>	<u>Equipment</u>	<u>Hours</u>	<u>Equip Cost</u>
	D147 NEW FLAT BED	4.00	
	G766 Ford	4.00	

<u>Materials Cost</u>	<u>Material Name</u>	<u>Amount Used (Units)</u>	<u>Measured In</u>	<u>Material Cost</u>
	Mortar mix	4.00	bags	

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

(GI 4)

CATCH BASIN INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 53' 57.33467" - W 83° 26' 10.90541"Location: 1131 Lake Welbrook Dr., Athens, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(CB20)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'52.08779"-W83°26'10.43840"

Location: 1260 Scarlet Oak Cir., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	<input checked="" type="radio"/> Yes <input type="radio"/> No	<i>Need to remove silt from structure.</i>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13886	Road Department	Michael Weathers		12/14/2021	7:30 AM
Location of Request					
1260 Scarlet Oak Circle					
Task	Date Completed				
Catch Basin Cleaning	12/14/2021				
Action for Task	Date of Action				
removed 1 ton of silt from structure	12/14/2021				
<u>Employee Hours and Cost</u>	<u># of Employees</u>	<u>Combined Hours</u>	<u>Cost of Action</u>		
	6	3.00			
<u>Subcontractor Hours and Cost</u>					
<u>Equipment Hours and Cost</u>	<u>Equipment</u>	<u>Hours</u>	<u>Equip Cost</u>		
	D020 FORD CAB AND CHASSIS(Water)	0.50			
	D146 FORD	0.50			
	D321 CAT EXCAVATOR	0.50			
	D494 DUMP TRUCK	0.50			
	G489 FORD	0.50			
<u>Materials Cost</u>					
Employee Costs for this Task:	\$0.00				
Subcontractor Costs for this Task:	\$0.00				
Equipment Costs for this Task:	\$0.00				
Materials Costs for this Task:	\$0.00				
Total All Employee Costs:	\$0.00				
Total All Subcontractor Costs:	\$0.00				
Total All Equipment Costs:	\$0.00				
Total All Materials Costs:	\$0.00				
GRAND TOTAL:	\$0.00				

(CB21)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'51.69325"-W83°26'10.79912"Location: 1251 Scarlet Oak Cir., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
"No dumping" educational marker	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Trash or debris at inlet opening	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	<i>Need to remove silt from structure.</i>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13887	Road Department	Michael Weathers		12/14/2021	7:30 AM
Location of Request					
1251 Scarlet Oak Circle					
Task	Date Completed				
Catch Basin Cleaning	12/14/2021				
Action for Task	Date of Action				
removed 1/2 ton of silt from structure	12/14/2021				
<u>Employee Hours and Cost</u>		# of Employees	Combined Hours	Cost of Action	
		6	3.00		
<u>Subcontractor Hours and Cost</u>					
<u>Equipment Hours and Cost</u>		Equipment	Hours	Equip Cost	
		D020 FORD CAB AND CHASSIS(Water)	0.50		
		D146 FORD	0.50		
		D321 CAT EXCAVATOR	0.50		
		D494 DUMP TRUCK	0.50		
		G489 FORD	0.50		
<u>Materials Cost</u>					
Employee Costs for this Task:	\$0.00				
Subcontractor Costs for this Task:	\$0.00				
Equipment Costs for this Task:	\$0.00				
Materials Costs for this Task:	\$0.00				
Total All Employee Costs:	\$0.00				
Total All Subcontractor Costs:	\$0.00				
Total All Equipment Costs:	\$0.00				
Total All Materials Costs:	\$0.00				
GRAND TOTAL:	\$0.00				

(CB22)

CATCH BASIN INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33° 53' 54.36449" - W 88° 26' 15.19604"

Location: 1301 Scarlet Oak Cir., Athens, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <u>No</u>	
"No dumping" educational marker	Yes / <u>No</u>	
Trash or debris at inlet opening	Yes / <u>No</u>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	<u>Yes</u> / No	<i>Need to clean out structure.</i>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <u>No</u>	
Pipes (roots, damaged, flow impeded)	Yes / <u>No</u>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13888	Road Department	Michael Weathers		12/14/2021	7:30 AM

Location of Request

1301 Scarlet Oak Circle

Task

Catch Basin Cleaning

Date Completed

12/14/2021

Action for Task

removed 1/2 ton of silt from structure

Date of Action

12/14/2021

Employee Hours and Cost
of Employees
Combined Hours
Cost of Action

6

3.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

D020 FORD CAB AND CHASSIS(Water)	0.50
D146 FORD	0.50
D321 CAT EXCAVATOR	0.50
D494 DUMP TRUCK	0.50
G489 FORD	0.50

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

CATCH BASIN INSPECTION CHECKLIST

(CB23)

Date: 12-6-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'54.5" W83°26'14.72678"Location: 1300 Scarlet Oak Cr., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	Need to remove silt from structure.
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13889	Road Department	Michael Weathers		12/14/2021	7:30 AM
Location of Request					
1300 Scarlet Oak Circle					
Task	Date Completed				
Catch Basin Cleaning	12/14/2021				
Action for Task	Date of Action				
removed 1 ton of silt from structure	12/14/2021				
<u>Employee Hours and Cost</u>	<u># of Employees</u>	<u>Combined Hours</u>	<u>Cost of Action</u>		
	6	3.00			
<u>Subcontractor Hours and Cost</u>					
<u>Equipment Hours and Cost</u>	<u>Equipment</u>	<u>Hours</u>	<u>Equip Cost</u>		
	D020 FORD CAB AND CHASSIS(Water)	0.50			
	D146 FORD	0.50			
	D321 CAT EXCAVATOR	0.50			
	D494 DUMP TRUCK	0.50			
	G489 FORD	0.50			
<u>Materials Cost</u>					
Employee Costs for this Task:	\$0.00				
Subcontractor Costs for this Task:	\$0.00				
Equipment Costs for this Task:	\$0.00				
Materials Costs for this Task:	\$0.00				
Total All Employee Costs:	\$0.00				
Total All Subcontractor Costs:	\$0.00				
Total All Equipment Costs:	\$0.00				
Total All Materials Costs:	\$0.00				
GRAND TOTAL:	\$0.00				

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'47.06506"-W83°26'1.30905"
Location: 1000 Arrowhead Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'46.75897"-W83°26'1.64323"

Location: 1001 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'47.45387"-W83°26'2.29918"Location: 1010 Arrowhead Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'47.48628"-W83°26'3.02897"Location: 1041 Arrowhead Rd, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'49.27789"-W83°26'4.74455"

Location: 1011 Arrowhead Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'51.09530"-W83°26'3.09743"Location: 1021 Etowah Ct., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'51.12099"-W83°26'2.31850"

Location: 1020 Etowah Ct., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N 33° 52' 51.18578" - W 83° 26' 1.85564"

Location: 1020 Etowah Ct., Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	<u>Need to clean structure of silt.</u>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	<u>Need to reposition structure</u>

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13968	Road Department	Michael Weathers		12/21/2021	7:30 AM

Location of Request:

1020 Etowah Court

Task	Date Completed
------	----------------

Catch Basin Cleaning	12/21/2021
----------------------	------------

Action for Task	Date of Action
-----------------	----------------

removed 6 tons of silt from catch basin and dit	12/21/2021
---	------------

Employee Hours and Cost	# of Employees	Combined Hours	Cost of Action
-------------------------	----------------	----------------	----------------

4	16.00
---	-------

Subcontractor Hours and Cost

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	D146 FORD	4.00	
	D321 CAT EXCAVATOR	4.00	
	D494 DUMP TRUCK	4.00	
	G489 FORD	4.00	

Materials Cost

Employee Costs for this Task:	\$0.00
Subcontractor Costs for this Task:	\$0.00
Equipment Costs for this Task:	\$0.00
Materials Costs for this Task:	\$0.00

Total All Employee Costs:	\$0.00
Total All Subcontractor Costs:	\$0.00
Total All Equipment Costs:	\$0.00
Total All Materials Costs:	\$0.00
GRAND TOTAL:	\$0.00

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N 33° 52' 51.55470" - W 83° 26' 2.06182"

Location: 1030 Etowah Ct, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'51.51024"-W83°26'6.13408"

Location: 1280 Arrowhead Rd, Watkinsville Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N133°52'52.75646"-W83°26'9.00648"Location: 1240 Arrowhead Rd, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'52.51101" - W83°26'11.18108"

Location: 1220 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'52.56007"-W83°26'12.51651"

Location: 1211 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'52.24181" - W83°26'12.58630"

Location: 1210 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'52.31605"-W83°26'13.87549"Location: 1201 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'51.87591"-W83°26'14.66613"

Location: 1191 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'51.64838"-W83°26'14.14123"

Location: 1190 Arrowhead Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'51.44625"-W83°26'18.93723"Location: 1030 Apache Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°32'51.31" W83°26'17.33776"Location: 1001 Apache Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'47.80792"-W83°26'12.80538"Location: 1151 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'47.59532"-W83°26'11.90239"

Location: 1110 Arrowhead Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'47.68218" - W83°26'10.15219"

Location: 1101 Arrowhead Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'48.40098"-W83°26'9.03832"Location: 1111 Arrowhead Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N 33° 52' 48.21858" - W 83° 26' 8.77160"Location: 1081 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'48.60037"-W83°26'8.65063"

Location: 1070 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): Lillian RhodesLocation/DescriptionID #: N33°52'48.875607"-W83°26'7.18046"Location: 1071 Arrowhead Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'57.08818"-W83°25'54.34993"Location: 1020 Tuckers Oaks Cir., Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'55.31808"-W83°25'55.22520"

Location: 1680 Hog Mtn. Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'52.95898"-W83°25'56.60325"

Location: 1700 Hog Mtn. Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'52.24645"-W83°25'56.84568"

Location: 1701 Hog Mtn Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'50.87928"-W83°25'57.72598"

Location: 1720 Hog Mtn, Rd., Watkinsville Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'49.6" W83°25'58.1" 7954"

Location: 1740 Hog Mtn. Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'42.33238"-W83°26'6.06793"

Location: 1840 Hog Mtn Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'40.89374"-W83°26'8.11886"

Location: 1860 Hog Mtn Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'40.32072"-W83°26'8.00898"

Location: 1870 Hog Mtn Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'40.28208"-W83°26'9.00252"

Location: 1880 Hog Mtn. Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'39.65725"-W83°26'9.80950"Location: 1890 Hog Mtn. Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-06-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'38.74" W83°26'10.97641"

Location: 1531 Boulder Crest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'38.06627"-W83°26'11.17228"

Location: 1911 Hog Mtn Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'37.58605"-W83°26'12.57280"

Location: 1910 Hog Mtn Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'36.98423"-W83°26'13.22686"

Location: 1920 Hog Mtn Rd, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N133°52'35.43290"-W83°26'15.36067"

Location: 1950 Hog Mtn. Rd., Watkinsville Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'34.86102"-W83°26'16.13901"Location: 1960 Hog Mtn Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'43.51955"-W83°26'16.58577"

Location: 1481 Bouldercrest Cir, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'43.83505"-W83°26'17.16432"

Location: 1480 Bouldercrest Cir., Watkinsville GA.
1471

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhoades

Location/Description

ID #: N33°52'44.94238"-W83°26'18.13658"

Location: 1451 Bouldercrest Cir, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'45.59" W83°26'19.03951"Location: 1440 Bouldercrest Cir., Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'45.90512"-W83°26'19.02354"Location: 1441 Boulder Crest Cir, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'46.77628"-W83°26'20.03842"Location: 1431 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-6-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'47.20718"-W83°26'20.88797"

Location: 1420 Bouldercrest Dr., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-6-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'47.93104"-W83°26'21.45799"Location: 1421 Bouldercrest Cir, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	