

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
12/7/2021	1101 Briarwood Trail	Pipe damaged but still functions		13930	12/17/2021

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'48.46751"-W83°26'21.65219"

Location: 1411 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'48.52179"-W83°26'22.46038"

Location: 1400 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'49.03" 183°26'22.86288"

Location: 1390 Bouldercrest Cr., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'50.04000"-W83°26'23.56527"

Location: 1380 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N133°52'51.37061"-W83°26'24.05611"

Location: 1360 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'53.76088"-W83°26'26.31450"

Location: 1340 Bouldercrest Cir, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'54.21063"-W83°26'25.93934"

Location: 1341 Bouldercrest C.R., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'54.17770"-W83°26'27.67076"

Location: 1320 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'54.79190"-W83°26'28.12618"

Location: 1320 B

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'55.07731" - W83°26'29.50080"

Location: 1300 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'53.14053"- W83°26'32.57565"

Location: 1240-1298 Boulderscrest Ctr, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'53.51247"-W83°26'32.33969"

Location: 1271 Boulder crest Cir, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'50.90418"-W83°26'33.78947"

Location: 1261 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'50.61383"-W83°26'34.26457"

Location: 1261 B Bouldercrest Cir., Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'48.55259"-W83°26'33.40290"

Location: 1221 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'48.18171"-W33°26'32.41198"

Location: 1201 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'47.37012"-W83°26'31.11833"Location: 1200 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'46.36801" - W83°26'31.28211"

Location: 1191 Bouldercrest Ctr, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'45.66" N 83°26'31.18514"

Location: 1181 Bouldercroft Cr., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'44.00822" - W83°26'29.14246"

Location: 1151 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'44.06673"-W83°26'28.30987"Location: 1140 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'43.79477"-W83°26'27.48832"Location: 1141 Bouldercrest Ctr., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'43.89711" - W83°26'27.25273"

Location: 1140 B Bouldercroft Dr., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'47.23314" - W83°26'26.51501"

Location: 1041 Briarwood Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'48.65599"-W83°26'27.02677"

Location: 1051 Briarwood Trail, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'49.50248"-W83°26'27.77725"Location: 1061 Briarwood Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'50.66447"-W83°26'28.92520"Location: 1081 Briarwood Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'51.28986"-W83°26'29.76791"Location: 1091 Briarwood Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'51.61310"-W83°26'29.86992"Location: 1090 Briarwood Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'52.40495"-W83°26'31.28857"

Location: 1101 Briarwood Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	<u>Pipe damaged but still functions</u>

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13930	Road Department	Michael Weathers		12/17/2021	7:30 AM

Location of Request

1101 Briarwood Trail

Task

Pipe Repair

Date Completed

12/17/2021

Action for Task

straightened ends of pipe

Date of Action

12/17/2021

Employee Hours and Cost
of Employees
Combined Hours
Cost of Action

4 4.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

G489 FORD 1.00

G771 1.00

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

DITCH INSPECTION CHECKLISTDate: 12-7-2023Inspector(s): William RhodesLocation/DescriptionID #: N33°52'52.73052"-W83°26'31.28380"Location: 1100 Briarwood Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'43.52110"-W83°26'26.83373"

Location: 1131 Bouldercast Ct, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'43.49946"-W83°26'25.47994"Location: 1130 Bouldercrest Cir, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William Rhodes**Location/Description**ID #: N33°52'42.66560" - W83°26'23.01234"Location: 1101 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'42.73635"-W83°26'23.10885"Location: 1120 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): Lillian RhodesLocation/DescriptionID #: N33°52'42.23279"-W83°26'22.21643"Location: 1100 Bouldercrest Cir, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'41.59368"-W83°26'21.62447"Location: 1100B Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'41.10313"-W83°26'21.26643"Location: 1101 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'43.70307"-W83°26'17.86969"

Location: 1151 Tuxedo Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'42, 97264"-W83°26'18, 33567"Location: 1140 Tuxedo Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'43.28234"-W83°26'18.51019"

Location: 1141 Tuxedo Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'42.33741"-W83°26'19.53494"

Location: 1131 Tuxedo Ln., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'Y2.02003"-W83°26'20.04971"Location: 1131 B Tuxedo Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'40.98233"-W83°26'20.70812"Location: 1050 Bouldercroft Cir., Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'40.73070"-W83°26'21.18374"Location: 1100 Tuxedo Ln., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'40.82612" - W83°26'21.48278"

Location: 1101 Tuxedo Ln., Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'40.18807"-W83°26'22.50706"

Location: 1091 Tuxedo Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'38.10497"-W83°26'23.84736"

Location: 1060 Tuxedo Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'36.84742"-W83°26'23.20144"

Location: 1060 Tuxedo Ln., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'36, 72701" - W83°26'23.29979"

Location: 1051 Tuxedo Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'35.72047"-W83°26'22.58450"Location: 1041 Tuxedo Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): Williams Rhodes

Location/Description

ID #: N33°52'35.90850" - W83°26'22.26672"

Location: 1040 Tuxedo Ln., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'35.10243"-W83°26'21.67363"Location: 1031 Tuxedo Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'34.68928"-W83°26'21.14217"Location: 1020 Tuxedo Ln., Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'34.40637"-W83°26'21.09579"Location: 1021 Tuxedo Ln., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'33.37759"-W83°26'18.17525"

Location: 1980 Hog Mtn Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'32.91075"-W83°26'18.77785"Location: 1980 Hog Mtn Rd. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'32.46522"-W83°26'19.25958"Location: 1001 Tuxedo Ln., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'32, 28901"-W83°26'19.38939"Location: 1990 Hog Mtn Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'31.81108"-W83°26'20.14658"Location: 2000 Hog Mtn Rd, Watkinsville Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N133°52'36.87588"-W83°26'16.22825"Location: 1010 Bouldercrest Cir, Watkinsville, GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'37.45974"-W83°26'16.84677"

Location: 1020 Bouldercrest Cir, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'37.24205"-W83°26'17.09585"Location: 1021 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N 33° 52' 38.14268" - W 83° 26' 18.06019"Location: 10103 Bouldercroft, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: 1133°52'39.03907"-W83°26'18.54085"Location: 1040 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'38.81133"-W83°26'18.81894"
Location: 1041 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'39.67091"-W83°26'19.70201"Location: 1051 Bouldercrest Cir., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'39.77123"-W83°26'19.50339"Location: 1050 Bouldercrest Cir., Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'44.03409"-W83°26'36.18042"Location: 1240 Woodlands Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhoadesLocation/DescriptionID #: N33°52'44.79580"-W83°26'35.66719'Location: 1241 Woodlands Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'46.38031"-W83°26'39.84509"

Location: 1170 Woodlands Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'45.46080"-W83°26'40.24498"
Location: 1170 B Woodlands Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'45.55727"-W83°26'40.38369"Location: 1170 C Woodlands Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'44.27622"-W83°26'40.10562"Location: 1160 Woodlands Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'43.90847"-W83°26'41.28985"Location: 1161 Woodlands Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'43.85957"-W83°26'42.07284"Location: 1010 Woodlands Ct., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N 33°52'43.56353" - W 83°26'41.18799"Location: 1001 Woodlands Ct., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'42.84702"-W83°26'39.91539"Location: 1140 Woodlands Rd., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'41.38203"-W83°26'39.64409"Location: 1130 Woodlands Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'40.41998"-W83°26'40.17541"Location: 1120 Woodlands Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'39.81977"-W83°26'40.95317"Location: 1110 Woodlands Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N133°52'40.16798"-W83°26'43.24026"Location: 1090 Woodlands Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-7-2021

Inspector(s): William Rhodes

Location/Description

ID #: N133°52'40.75107"-W83°26'43.95094"

Location: 1081 Woodlands Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'40.62905"-W83°26'44.87554"
Location: 1070 Woodlands Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-7-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°52'39.54506"-W83°26'47.66357"Location: 1050 Woodlands Rd, Watkinsville, GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	