

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
12/28/2021	4071 Mars Hill Rd	Need to be repaired or replaced		14089	1/24/2022
		Entrance of Racetrack			
	1011 Commerce Dr	Need to remove debris and make repairs	2	14090	1/24/2022
		See remarks			
	1150 Julian Dr	Grout work needed back of curb		14131	1/31/2022

CATCH BASIN INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°55'13.25714"-W83°30'51.34433"Location: 2403 Monroe Hwy, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

At Race Track
Entrance on 1

Date: 12-28-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°55'12.39659" - W83°30'50.38883"Location: 4071 Main Hill Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	Need to be repaired and/or replaced
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14089	Road Department	Michael Weathers		12/28/2021	7:30 AM

Location of Request

4071 Mars Hill Rd

Task
Date Completed

1/24/2022

Catch Basin Repair

Date of Action

1/24/2022

Action for Task

inspected catch basin, it was repaired by prop

Employee Hours and Cost
of Employees
Combined Hours
Cost of Action

4

4.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

D146 FORD	1.00
D321 CAT EXCAVATOR	1.00
D494 DUMP TRUCK	1.00
G489 FORD	1.00

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

CBI

CATCH BASIN INSPECTION CHECKLIST

Date: 12-28-2021Inspector(s): William RhodeLocation/DescriptionGPS Point Name: N33°55'5.37863"-W83°30'33.23458"Location: 3901 Mars Hill Rd. CBI Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CB2

CATCH BASIN INSPECTION CHECKLIST

Date: 12-28-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°55'5.56872"-W83°30'39.822941"Location: 2771 Malcolm Bridge Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CB3

CATCH BASIN INSPECTION CHECKLIST

Date: 12-28-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°55'6.33591"-W83°30'31.88888"Location: 3901 Mais Hll Rd., Bogalusa GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

JB

CATCH BASIN INSPECTION CHECKLIST

Date: 12-28-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°55'6.06730" - W83°30'30.44611"Location: 1010 Commerce Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CB4

CATCH BASIN INSPECTION CHECKLIST

Date: 12-28-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°55'5.90174"-W83°30'32.06752"Location: 1010 Commerce Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'54.5" W83°30'5.78950"Location: 3681B Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'50.33332"- W83°29'50.04639"Location: 1186 Shenandoah Dr. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Culvert

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'11.44409"-W83°30'49.95107"

Location: 4071B Mars Hill Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'11.35514"-W83°30'49.69992"

Location: 4071 C Mars Hill Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'10.41006"-W83°30'47.23491"

Location: 4041 Mars Hill Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'8.69338"-W83°30'39.35110"Location: 1021 Baker Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'8.63767"-W83°30'39.65247"

Location: 1021B Baker Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'6.94889"-W83°30'35.55832"

Location: 2771 Malcom Bridge Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William Rhodes*Culvert Out
Down from round*Location/DescriptionID #: N33°55'7.68353"-W83°30'36.11230"Location: 1011 Commerce Dr. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	<i>Need to remove debris & make repairs to Out pipe.</i>

*Owner
Issue*

** Silt fence along stream need to be removed
Owner need to obtain proper permit for
disturbance in buffer area.*

** Must Contact Gaby for further instructions*

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14090	Road Department	Michael Weathers		12/28/2021	7:30 AM

Location of Request

1011 Commerce Drive

Task

Pipe Cleaning

Date Completed

1/24/2022

Action for Task

cleaned out 2 tons of debris from inlet of pipe,

Date of Action

1/24/2022

Employee Hours and Cost

of Employees

Combined Hours

Cost of Action

4

4.00

Subcontractor Hours and Cost

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	D146 FORD	1.00	
	D321 CAT EXCAVATOR	1.00	
	D494 DUMP TRUCK	1.00	
	G489 FORD	1.00	

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'4.93455" - W83°30'28.78304"Location: 3881 Mars Hill Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'4.42638" - W83°30'27.27776"

Location: 3841 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'3.10037"-W83°30'24.13933"

Location: 3831 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'2.56988"-W83°30'23.32945"Location: 3831B Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'1.60144"-W83°30'21.17595"Location: 3801 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'2.12052" - W83°30'20.99172"Location: 1001 Bell Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'59.62649"- W83°30'17.61697"

Location: 3771 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'0.76108"-W83°30'18.46918"

Location: 1030 Bell Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'0.12730"-W83°30'17.32452"Location: 1030 B Bell Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'59.54965"-W83°30'16.08049"

Location: 3760 Mass Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'59.16564"-W83°30'17.03493"

Location: 3761 Mars Hill Rd. Watkinsville Ga.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'58.81410"-W83°30'16.01555"Location: 3761B Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'57.88844" - W83°30'14.13563"

Location: 3731 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'57.58175"-W83°30'13.44477"Location: 3721 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'56.34783"-W83°30'10.66148"Location: 3701 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'57.31788"-W83°30'11.97989"

Location: 3701 B Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'55.22018"-W83°30'7.45264"

Location: 3681 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'53.58950"-W83°30'1.28337"Location: 3625 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Culvert

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'53.19080"-W83°29'59.90454"

Location: 3591 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'52.98546"-W83°29'58.49673"Location: 3581 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'3.95794"-W83°29'39.91795"Location: 1161 Long Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'1.90010"- W83°29'40.84388"Location: 1151 Long Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'0.93495" W83°29'41.35792"Location: 1131 Long Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'57.46583"-W83°29'43.58091"

Location: 1061 Long Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'15.22315"-W83°30'2.58461"

Location: 1211 Julian Dr., Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'13.34491"-W83°30'3.43976"Location: 1181 Julian Dr. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'10.93277"-W83°30'3.44220"Location: 1161 Julian Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'5.29794"-W83°30'3.58411"Location: 1171 Julian Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhoadesLocation/DescriptionGPS Point Name: N33°55'7.12928"-W83°30'3.14655"Location: 1150 Julian Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	Grout work needed back of curb
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14131	Road Department	Michael Weathers		12/28/2021	7:30 AM
	Location of Request				

Location of Request

1150 Julian Drive

1150 Julian Drive

Task

Catch Basin Repair

Date Completed

1/31/2022

Action for Task

put dirt in sink hole behind curbing, grouted and

Date of Action

1/31/2022

Employee Hours and Cost

of Employees

Combined Hours

Cost of Action

5

5.00

Subcontractor Hours and Cost

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	D947 FORD FLATBED	1.00	
	G489 FORD	1.00	
	G771	1.00	

Materials Cost	Material Name	Amount Used (Units)	Measured In	Material Cost
	Dirt	1.00	Ton	
	Mortar mix	1.00	bags	

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: **\$0.00**

Equipment Costs for this Task: **\$0.00**

Materials Costs for this Task: \$0.00

Total All Employee Costs:	\$0.00
Total All Subcontractor Costs:	\$0.00
Total All Equipment Costs:	\$0.00
Total All Materials Costs:	\$0.00
GRAND TOTAL:	<hr/> \$0.00

DITCH INSPECTION CHECKLIST

Date: 12-28-2021

Inspector(s): William Rhodes

Location/Description

ID #: N33°55'7.08" W83°30'3.62"29"

Location: 1151 Julian Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 12-28-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'59.87121"-W83°30'4.96199"Location: 1051 Julian Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	