

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
12/29/2021	3101 Mars Hill rd	Sink hole developing on the slope		14132	1/31/2022
	Entrance of Sagefield Dr	Pipe need to be dug out for proper flow	1	14091	1/24/2022
	2920B Mars Hill Road	Pipe needs fill dirt added to pipe head		14133	1/31/2022

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'47.42490"-W83°29'41.84702"Location: 1176 Allegheny Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

JB

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-27-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'44.53336"-W83°29'34.69176"Location: 1011 Oaklake Trail Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'36.02603"-W83°28'30.95809"Location: 2899 Mars Hill Rd. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'35.64494"-W83°28'30.65014"Location: 3279 Rocky Branch Rd. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 54' 34.65" / W 83° 28' 30.35" / 27"Location: 3279B Rocky Branch Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°05'13.54" W83°28'29.15484"Location: 3220 Rocky Branch Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'36.06663"-W83°28'29.21086"Location: 2771 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'34.27208"-W83°28'26.14549"Location: 2695 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'26.88092" - W83°28'7.51571"Location: 2521 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'25.90378"-W83°28'4.95411"Location: 2571 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 54' 25.15100" - W 83° 28' 2.91612"Location: 2523 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'24.50047"-W83°28'3.08068"Location: 2523B Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'24.12464"-W83°28'3.29010"Location: 1000 Hollow Creek Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
"No dumping" educational marker	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Trash or debris at inlet opening	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'24.39069"-W83°28'1.99819"Location: 2521 Mars Hill Rd, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'23, 90390"-W83°28'0.56877"Location: 2521 B Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33° 54'23.5" S 78°47' - W83°27'59.08321"Location: 2571 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'22.99214"-W83°27'58.20191"Location: 2571B Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

## Location/Description

ID #: N33°54'47.33564"-W83°29'40.08637"

Location: 3430 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'46.35324"-W83°29'37.80214"Location: 3400 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N 33° 54' 44.35678" - W 83° 29' 34.40558"Location: 1011 B Oaklake Trail, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'44.63566"-W83°29'33.38391"Location: 3360 Mars Hill Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'43.07641"-W83°29'29.89136"Location: 3330 Mars Hill Rd. Watkinsville GA.


Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'39.18566"-W83°29'22.28491"Location: 3301 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'38.53538"-W83°29'20.73891"Location: 3301B Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST***Culvert**Next to Briar Lake Rd. & Mars Hill Rd.*Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'36.44998"-W83°29'12.64381"Location: 3101 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	Sink hole developing on the slope
Vegetation maintained to capture sediment	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Excessive siltation buildup	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request																								
14132	Road Department	Michael Weathers		12/29/2021	7:30 AM																								
<b>Location of Request</b>																													
3101 Mars Hill Rd																													
Task		Date Completed																											
Sink hole		1/31/2022																											
Action for Task		Date of Action																											
filled in sink hole with dirt		1/31/2022																											
<u>Employee Hours and Cost</u>	<u># of Employees</u>	<u>Combined Hours</u>	<u>Cost of Action</u>																										
	5	5.00																											
<b>Subcontractor Hours and Cost</b>																													
<table border="1"> <thead> <tr> <th>Equipment Hours and Cost</th> <th>Equipment</th> <th>Hours</th> <th>Equip Cost</th> </tr> </thead> <tbody> <tr> <td></td><td>D321 CAT EXCAVATOR</td><td>1.00</td><td></td></tr> <tr> <td></td><td>D494 DUMP TRUCK</td><td>1.00</td><td></td></tr> <tr> <td></td><td>D947 FORD FLATBED</td><td>1.00</td><td></td></tr> <tr> <td></td><td>G489 FORD</td><td>1.00</td><td></td></tr> <tr> <td></td><td>G771</td><td>1.00</td><td></td></tr> </tbody> </table>						Equipment Hours and Cost	Equipment	Hours	Equip Cost		D321 CAT EXCAVATOR	1.00			D494 DUMP TRUCK	1.00			D947 FORD FLATBED	1.00			G489 FORD	1.00			G771	1.00	
Equipment Hours and Cost	Equipment	Hours	Equip Cost																										
	D321 CAT EXCAVATOR	1.00																											
	D494 DUMP TRUCK	1.00																											
	D947 FORD FLATBED	1.00																											
	G489 FORD	1.00																											
	G771	1.00																											
<u>Materials Cost</u>	<u>Material Name</u>	<u>Amount Used (Units)</u>	<u>Measured In</u>	<u>Material Cost</u>																									
	Dirt	5.00	Ton																										
<b>Employee Costs for this Task:</b>	\$0.00																												
<b>Subcontractor Costs for this Task:</b>	\$0.00																												
<b>Equipment Costs for this Task:</b>	\$0.00																												
<b>Materials Costs for this Task:</b>	\$0.00																												
<b>Total All Employee Costs:</b>	\$0.00																												
<b>Total All Subcontractor Costs:</b>	\$0.00																												
<b>Total All Equipment Costs:</b>	\$0.00																												
<b>Total All Materials Costs:</b>	\$0.00																												
<b>GRAND TOTAL:</b>	<b>\$0.00</b>																												

# DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

## Location/Description

ID #: N33°54'36.25531"-W83°29'8.88743"

Location: 3131 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'36.11106"-W83°29'7.23983"

Location: 3111 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**

Entrance of  
Sagefield Dr. & Mars Hill Rd.

Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'36.42817" - W83°29'5.17611"Location: 1 Sagefield Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	Pipe need to be dug out for proper flow.

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14091	Road Department	Michael Weathers		12/29/2021	7:30 AM

## Location of Request

Entrance of Sagefield Drive

## Task

Drainage problem

## Date Completed

1/24/2022

## Action for Task

cleaned 1 ton of debris out inlet of catch basin

## Date of Action

1/24/2022

## Employee Hours and Cost

## # of Employees

## Combined Hours

## Cost of Action

4

4.00

## Subcontractor Hours and Cost

## Equipment Hours and Cost

## Equipment

## Hours

## Equip Cost

D146 FORD

1.00

D321 CAT EXCAVATOR

1.00

D494 DUMP TRUCK

1.00

G489 FORD

1.00

## Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

**GRAND TOTAL:** \$0.00

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'37.00/23"-W83°28'59.43082"

Location: 3010 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'36.59399"-W83°28'57.15572"Location: 2981 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'37.06313"-W83°28'56.61239"Location: 2990 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

## Location/Description

ID #: N33°54'37.38407"-W83°28'50.97090"

Location: 2940 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'37.56549"-W83°28'49.75195"

Location: 2930 Mars Hill Rd, Watkinsville, Ga.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

## Location/Description

ID #: N33°54'37.18789"-W83°28'49.29009"

Location: 2961 Mars Hill Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'37.72032"-W83°28'47.91449"

Location: 2920 Mars Hill Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# DITCH INSPECTION CHECKLIST

Culvert

Date: 12-29-2021

Inspector(s): William Rhodes

## Location/Description

ID #: N33°54'37.67773"-W83°28'47.04015"

Location: 2920B Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	Pipe need fill dirt added to pipe head.
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14133	Road Department	Michael Weathers		12/29/2021	7:30 AM

**Location of Request**

2920B Mars Hill Rd

**Task**

Pipe Repair

**Date Completed**

1/31/2022

**Date of Action**

1/31/2022

**Action for Task**

put dirt around end of pipe

Employee Hours and Cost
# of Employees
Combined Hours
Cost of Action

5 5.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

D321 CAT EXCAVATOR	1.00
D494 DUMP TRUCK	1.00
D947 FORD FLATBED	1.00
G489 FORD	1.00
G771	1.00

Materials Cost
Material Name
Amount Used (Units)
Measured In
Material Cost

Dirt

2.00

Ton

**Employee Costs for this Task:** \$0.00

**Subcontractor Costs for this Task:** \$0.00

**Equipment Costs for this Task:** \$0.00

**Materials Costs for this Task:** \$0.00

**Total All Employee Costs:** \$0.00

**Total All Subcontractor Costs:** \$0.00

**Total All Equipment Costs:** \$0.00

**Total All Materials Costs:** \$0.00

**GRAND TOTAL:** \$0.00

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'37.40093"-W83°28'46.35801"

Location: 2941 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'37.79719"- W83°28'45.96545"

Location: 2900 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'38.02865"-W83°28'43.87410"Location: 2890 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'38.25269" - W83°28'41.08980"Location: 1015 Fieldstone Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'38.25098"-W83°28'37.51753"Location: 2840 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'37.98279"-W83°28'36.48462"

Location: 2830 Mars Hill Rd. Watkinsville Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'37.79351"- W83°28'37.50877"Location: 2899 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

## Location/Description

ID #: N33°54'37.50073"-W83°28'41.92694"

Location: 1011 Paul Ridge Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'37.00613"-W83°28'33.69850"Location: 2801 Mars Hill Rd. i Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'32.95096"-W83°28'23.03336"Location: 2769 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'33.9/552"-W83°28'25.46063"Location: 3220 Rocky Branch Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

## Location/Description

ID #: N33°54'33.83806" - W83°28'23.85684"  
Location: 27693 Mars Hill Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'31.64114"-W83°28'20.11630"

Location: 2667 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-29-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°54'28.79168"-W83°28'12.76060"Location: 2603 Mars Hill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°54'27.90016" - W83°28'11.85809"

Location: 1000 Paandra Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# DITCH INSPECTION CHECKLIST

Date: 12-29-2021

Inspector(s): William Rhodes

## Location/Description

ID #: N33°41'27.09851"-W83°28.8.57667"

Location: 2601 Mars Hill Rd. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	