

N33°54'24.89489" - W83°28'45.28643"  
Canyon Creek

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1407

Location: 1131 Paul Ridge Rd. Watkinsville GA. Canyon Creek S/D

Receiving Stream & Watershed Name: Unnamed tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'25.87982"-W83°28'45.83229"

Canyon Creek

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1401

Location: 1131B Paul Ridge Rd. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'26.03254"-W83°29'2.43909"

Canyon Creek

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1410

Location: 1041 West Canyon Creek Ct. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°54'40.98072"-W83°28'42.46184"  
Field Stone

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1415

Location: 1020 Fieldstone Rd. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'41.33378" - W83°28'46.58204"

Fieldstone

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1394

Location: 1085 Fieldstone Rd. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°54'19.61597"-W83°28'46.04394"

Sterling Mills

# **DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes + Matt Gilstrap

## **A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## **B. Outfall Location/Description**

ID Number: 1619

Location: 1 Town Hall Pl. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

## **C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## **D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## **E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## **Notes/Follow-Up**

---

---

---

---

---

N33°54'20.57162"-W83°28'47.49401"  
Sterling Mills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1630

Location: 1161 Paul Ridge Rd. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'8.29957" - W83°29'14.12502"  
Rocky Branch Rd.

# **DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

## **A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## **B. Outfall Location/Description**

ID Number:                     

Location: 1 Rocky Branch Rd. Watkinsville GA

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

## **C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

## **D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

X Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

X Fluoride:                                     

## **E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

## **Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'12.99621"-W83°29'49.64964"

Old Waverly

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: \_\_\_\_\_

Location: 1001 Hammond Creek Trail, Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°54'32.90845"-W83°30'18.25670"

Fern Hill

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1589

Location: 1384 Fern Hill Rd. Bogart GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'29.83580"-W83°30'3.19760"

Fern Hill

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1592

Location: 1516 Bracken Ct. Bogart GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect-Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°54'26.57969"-W83°30'2.74331"

Fern Hill

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1595

Location: 1636 Broken Ctr., Bogart GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'25.77052"-W83°30'7.38249"

Fern Hill

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:       

Location: 3249 Fern Hill Rd. Bogart GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect-Ditch

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:       

Odor:       

Floatables (includes oil sheen, suds, & sewage):       

Biological Indicators (algae, emergent vegetation, etc.):       

Other:       

**D. Lab Analysis Results**

pH:       

Conductivity:       

☒ Surfactants:       

Ammonia:       

Turbidity:       

☒ Fluoride:       

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:       

Results:       

**Notes/Follow-Up**

N33°54'37.28613"-W83°29'36.01038"

Oaklake

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes + Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1030 Oaklake Trl. Watkinsville GA.

Receiving Stream & Watershed Name: Pond

Outfall Type: Pipe - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                     

Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'25.63333" - W83°29'43.04628"

Oak Lake

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1191 Oak Lake Terr. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Ditch

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'36.62336"-W83°29'20.27399"

Brockton Place

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-12-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1643

Location: 1011 Brockton Ct. Watkinsville GA.

Receiving Stream & Watershed Name: Ditch

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_ Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_ Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_ ☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°55'28.74847" - W83°32'42.44939"

Planters Ridge

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1030 Planters Trl. Bogart GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Mc Nutt Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°55'12.23080"-W83°31'58.30879"

Fernwood

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 157

Location: 1010 Fernwood Dr., Bogart GA.

Receiving Stream & Watershed Name: Ditch

Outfall Type: Indirect - Earth

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°55'14.75927"-W83°32'16.27527"

Trotters Walk

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 3180 Monroe Hwy, Bogart GA.

Receiving Stream & Watershed Name: Unnamed tributary to McNutt Creek

Outfall Type: Indirect-Ditch

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Foatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°55'19.35064" - W83°32'9.47999"

Trotters Walk

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1082 Center Bend

Receiving Stream & Watershed Name: Unnamed Tributary to McNitt Creek

Outfall Type: Indirect - Pitch

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'8.99592" - W83°28'13.11248"

Hollow Creek Ln.

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1180 Hollow Creek Ln. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'8.83555"-W83°27'59.45447"

Hollow Creek Ln.

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1330 Hollow Creek Ln.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Direct - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'11.13356" - W83°27'54.47089"

Hollow Creek Ln.

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1380 Hollow Creek Ln. Wat Kingsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                     

Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

X Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

X Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'7.78193"-W83°26'35.73105"

Welbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Mott Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 490

Location: 1161 Nona Dr. Athens GA.

Receiving Stream & Watershed Name: Barbar Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'0.49246"-W83°26'30.35847"

Welbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 494

Location: 1091 Nona Rd. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'7.21782" - W83°26'27.45269"

Welbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 500

Location: 1041 Nona Dr. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'12.73103" - W83°26'26.68206"

Welbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes + Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 509

Location: 1050 Scott Terrace Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Retch

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'18.20660"-W83°26'22.94218"

Wellbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 512

Location: 1020 Sylvia Ct. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'27.64078"-W83°26'25.72239"

Welbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 523

Location: 1180 Beverly Dr. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'21.82524"-W83°26'32.08068"

Welbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 529

Location: 1030 Chris Ct. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'20.07149"-W83°26'32.40320"

Wellbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes + Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 703  
Location: 1040 Beverly Dr. Athens GA.  
Receiving Stream & Watershed Name: Barber Creek  
Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_  
Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_  
Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_  
Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_ Conductivity: \_\_\_\_\_  
☒ Surfactants: \_\_\_\_\_ Ammonia: \_\_\_\_\_  
Turbidity: \_\_\_\_\_ ☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_  
Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'25.38404" - W83°26'11.66400"

Welbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 704

Location: 1450 Beverly Dr. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'22.91583"-W83°26'7.14219"

Welbrook Farms

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-13-2022

Inspector(s): William Rhodes

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 709

Location: 1410 Beverly Dr. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Foatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'44.62338"-W83°26'22.64446"

Lake Welbrook

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 464

Location: 1011 Magnolia Dr. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'56.80559" - W83°26'22.44222"

Lake Welbrook

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 469

Location: 1060 Scarlet Oak Cir. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'9.93310"-W83°26'19.13551"

Lake Welbrook

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 478

Location: 1001 Lake Welbrook Dr.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'52.18754" - W83°26'4.09568"

Lake Welbrook

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gillstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 452

Location: 1211 Lake Welbrook Dr. Athens GA.

Receiving Stream & Watershed Name: Unnamed tributary to Barber Creek

Outfall Type: Direct - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'31.11979"-W83°25'51.71771"

Ridge Pointe

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes + Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: -

Location: 1090 Ridge Point Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'14.33877" - W83°26'59.53307"

Birchmore Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 961

Location: 1111 Creekshore Dr. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Direct - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'0.29299"-W83°26'40.84151"

Birchmore Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 965

Location: 1031 Twin Lakes Rd. Athens GA.

Receiving Stream & Watershed Name: Unnamed tributary to Barber Creek

Outfall Type: Direct - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'40.62027"-W83°26'6.51100"

Hog Mountain Rd.

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes + Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 84

Location: 1870 Hog Mountain Rd., Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'39.94734" - W83°26'35.16913"

Timber Mill

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1031 Timber Mill Run

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                     

Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

X Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

X Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'39.21597" - W83°26'53.92532"

1260 Mars Hill Rd.

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: ~~1444~~ 1444

Location: 1260 Mars Hill Rd. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barker Creek

Outfall Type: ~~Direct~~ Indirect - ~~concrete~~ Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'23.82028" - W83°25'58.34795"

# **DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstrap

## **A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## **B. Outfall Location/Description**

ID Number: -

Location: 1070 Stonebridge Cir, Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary

Outfall Type: Indirect - Pitch

## **C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## **D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## **E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## **Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'27.47396" - W83°25'52.36616"

# **DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes & Matt Gilstrap

## **A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## **B. Outfall Location/Description**

ID Number:                     

Location: 1030 Stonebridge Cir. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary

Outfall Type: Indirect - Metal

## **C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

## **D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

## **E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

## **Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'28.72048" - W83°35'47.90176"

# **DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes + Matt Gilstop

## **A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## **B. Outfall Location/Description**

ID Number:                     

Location: 1210 Stonebridge Cir. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary

Outfall Type: Indirect - Metal

## **C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

## **D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

## **E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

## **Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°50'18.17868" - W83°26'20.61232"

Southwind Manor

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-14-2022

Inspector(s): William Rhodes + Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 0

Location: 1070 Manor Ridge Dr. Bishop GA.

Receiving Stream & Watershed Name: Greenbrier Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'24.58299" - W83°23'47.79615"

Calls Creek

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 630

Location: 1011 Calls Creek Ct. Watkinsville GA.

Receiving Stream & Watershed Name: Calls Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'29.23044"-W83°23'46.07073"

Calls Creek

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 628

Location: 1050 Calls Creek Ct. Watkinsville GA.

Receiving Stream & Watershed Name: Calls Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'30.55519"-W83°23'40.29459"

*Colls Creek*

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 612  
Location: 1200 Colls Creek Dr. Watkinsville GA.  
Receiving Stream & Watershed Name: Colls Creek  
Outfall Type: Direct-Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_  
Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_  
Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_  
Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_ Conductivity: \_\_\_\_\_  
☒ Surfactants: \_\_\_\_\_ Ammonia: \_\_\_\_\_  
Turbidity: \_\_\_\_\_ ☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_  
Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°52'33.78181" W83°23'36.30592"

Colls Creek

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 608

Location: 1281 Colls Creek Cir.

Receiving Stream & Watershed Name: Colls Creek

Outfall Type: Direct - ~~Concrete~~ Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Knob Creek Dr.

Date: 4-15-2022

Date: 9-13-2022  
Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: [REDACTED]

ID Number: \_\_\_\_\_  
Location: 1080 Knob Creek Dr. Athens GA.

Location: 1050 Union Creek Dr. Hering Co.  
Receiving Stream & Watershed Name: Oconee River Unnamed Tributary

Outfall Type: Indirect - Concrete

### C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

### Notes/Follow-Up

---

---

---

---

N33°53'39.51524" W83°24'10.49800"

Tybee Trace

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1020 Tybee Trace, Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Oconee River

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                     

Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'37.27680"-W83°21'16.33018"

Powell Ct.

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes + Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1020 Powell Ct Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Oconee River

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Foatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

X Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

X Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'29.93391" - W83°24'17.99418"

Knob Creek

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes + Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: -

Location: 1250 Knob Creek Dr.

Receiving Stream & Watershed Name: Unnamed Tributary to Oconee River

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33° 53' 35.12627" - W83° 24' 22.20064"

Knob Creek Dr.

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes & Matt Gilsprap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: -

Location: 1250 Knob Creek Dr. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Oconee Creek

Outfall Type: Indirect - Concrete Pitch

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Robinson Ct. lost Retention Pond

Date: 4-15-2022

Date: 7-15-2022  
Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: \_\_\_\_\_

ID Number: \_\_\_\_\_  
Location: 1061 Robinson Ct. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Oconee River

Outfall Type: Indirect - Concrete

### C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

#### D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

### Notes/Follow-Up

---

---

---

---

---

N33°52'54.91107"-W83°24'45.79034"

Summit Grove

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-15-2022

Inspector(s): William Rhodes & Matt Gilstrap

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number:                     

Location: 1 Summit Grove Dr. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Cobs Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                     

Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

**D. Lab Analysis Results**

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID:                                     

Results:                                     

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Summit Oaks Pr.

Date: 4-15-2022

Inspector(s): William Rhodes & Matt Gilstrap

☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

ID Number: \_\_\_\_\_

ID Number: \_\_\_\_\_  
Location: 1041 Summit Oaks Dr. Watkinsville GA.  
Receiving Stream & Watershed Name: Unimproved Tributary to Calls Creek  
Outfall Type: Indirect - Concrete

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_  
 Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_  
 Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_  
 Other: \_\_\_\_\_

pH: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Turbidity: \_\_\_\_\_

Conductivity: \_\_\_\_\_

Ammonia: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

### Notes/Follow-Up

---

---

---

---

---

Summit Oaks Dr.

Date: 4-15-2022

Date: 9-15-2020

Date: 7-15-2024  
Inspector(s): William Rhodes & Matt Gilstrap

☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

ID Number:                     

ID Number:                     

ID Number:                       
Location: 1150 Summit Oaks Dr. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Calls Creek

Outfall Type: Indirect - Metal

Dry Weather Flow Observed? ☐ No ☒ Yes (if yes, complete sections C, D & E below)

Dry Weather Flow Observed? ☐ No ☒ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

Sample ID: \_\_\_\_\_

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

### Notes/Follow-Up

---

---

---

---

---

N33°53'45.14958"-W83°24'38.70597"  
Crystal Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 758

Location: 1851 Wild Azalea Ln, Athens GA.

Receiving Stream & Watershed Name: Barber Creek - Ditch

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'51.84495"-W83°24'48.30881"  
Crystal Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 759

Location: 1061 Ashwood Ln. Athens GA.

Receiving Stream & Watershed Name: Barber Creek - Ditch

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'38.38389"-W83°25'35.14440"

Crystal Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 765

Location: Shoals Pte Athens GA.

Receiving Stream & Watershed Name: Unnamed tributary to Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'27.20254"-W83°25'22.44849"

Crystal Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 775

Location: 1000 Wild Azalea Ln. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'38.42565"-W83°25'6.15116"

Crystal Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 776

Location: 1030 Hollyberry Ln. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'33.52781"-W83°25'8.37924"

Crystal Hills

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 783

Location: 1579 Crystal Hills Dr. Athens GA

Receiving Stream & Watershed Name: Ditch - Barber Creek

Outfall Type: Indirect - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N 33°54'27.84945" - W 83°25'1.88254"

Crystal Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 802

Location: 1490 Crystal Hills Dr. Athens GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'23.63787"-W83°25'0.51975"

Crystal Hills

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 804  
Location: 1442 Crystal Hills Dr. Athens GA.  
Receiving Stream & Watershed Name: Barber Creek - Ditch  
Outfall Type: Indirect - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_ Conductivity: \_\_\_\_\_  
☒ Surfactants: \_\_\_\_\_ Ammonia: \_\_\_\_\_  
Turbidity: \_\_\_\_\_ ☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_  
Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°54'7.72137"-W83°24'58.22448"  
Crystal Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 378  
Location: 1301 Crystal Hills Dr. Athens GA.  
Receiving Stream & Watershed Name: Ditch - Barber Creek  
Outfall Type: Direct - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'5.69556"-W83°24'53.84527"

Crystall Hills

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 812

Location: 1141 Crystal Hills Dr. Athens GA.

Receiving Stream & Watershed Name: Barker Creek

Outfall Type: Direct - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'1.13919"-W83°24'51.02159"

Crystal Hills

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 813

Location: 1181 Crystal Hills Dr. Athens GA.

Receiving Stream & Watershed Name: Barber Creek - Ditch

Outfall Type: Direct - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N 33° 54' 38.13946" - W 83° 24' 14.52328"  
Highland Hills Village

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1450

Location: 1051 Cherry Hills Ct. Athens GA.

Receiving Stream & Watershed Name: McNutt Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'38.13158" - W83°24'10.66578"

Highland Hills Village

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1455

Location: 1026 Cherry Hills Ct. Athens GA.

Receiving Stream & Watershed Name: Unnamed tributary to McMill Creek - Pitch

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'30.83458" - W83°24'33.03312"

Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 397

Location: 1261 White Oak Dr. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'35.22465"-W83°24'48.41838"  
Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 398

Location: 1401 White Oaks Dr. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'33.11867"-W83°24'44.34154"

Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 399

Location: 1120 Sweetwater Cir. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'32.78833" W83°24'43.86928"

Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 400

Location: 1115 Sweetwater Cir. Athens GA.

Receiving Stream & Watershed Name: Unnamed tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'36.66856"-W83°24'39.99651"

Highland Oaks

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 401  
Location: 1080 Sweetwater Cir. Athens GA.  
Receiving Stream & Watershed Name: Unnamed tributary to McMillan Creek  
Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°54'36.51738"-W83°24'40.06289"  
Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 402

Location: 1041 Sweetwater Cir. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'35.62484"-W83°24'30.32724"

Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 403

Location: 1140 Kings Mill Run Athens GA

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'39.20135"-W83°24'33.13284"  
Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 404

Location: 1071 Scurwood Ct. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'38.86999"-W83°24'25.13245"  
Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 405

Location: 1022 Alpine Ct. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'37.75302"-W83°24'19.18112"

Highland Oaks

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 406

Location: 1020 Creek View Ct. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: \_\_\_\_\_

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'56.73691"-W83°24'23.04368"  
Spartan Ln.

**DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 4-4-2022

Inspector(s): William Rhodes - Jerry Marshall - Michael R. Compton

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: \_\_\_\_\_

Location: 1111 Spartan Ln. Athens GA.

Receiving Stream & Watershed Name: Unnamed Tributary to Barber Creek

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'51.27196"-W83°27'31.86090"

## DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-28-2022

Inspector(s): William Rhodes

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 902

Location: 1081 Pebblestone Dr. Watkinsville GA.

Receiving Stream & Watershed Name: Parker Branch

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'1.77598"-W83°27'40.04273"

## DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-28-2022

Inspector(s): William Rhodes

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 912

Location: 1051 River Haven Ln. Watkinsville GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect - Metal

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°54'22.99409" - W83°27'58.09658"

## DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-28-2022

Inspector(s): William Rhodes

### A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

### B. Outfall Location/Description

ID Number: 1444

Location: 1 Old Moss Hill Rd. Watkinsville GA.

Receiving Stream & Watershed Name: Ditch

Outfall Type: Indirect - Concrete

### C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

### D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

### E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

### Notes/Follow-Up

---

---

---

---

---

N33°55'37.80679" - W83°33'5.17027"

## DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-28-2022

Inspector(s): William & Tabitha

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1579

Location: 1180 Cobbstone Ln. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed tributary to McNutt Creek

Outfall Type: Direct - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°55'35.68328"-W83°33'1.59338"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-28-2022

Inspector(s): William & Tabitha

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1580

Location: 1110 Cobblestone Ln. Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed tributary to ~~Shoals~~ McNutt Creek

Outfall Type: Direct - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°55'36.00515"-W83°33'2.50999"

## DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-28-2022

Inspector(s): William & Tabitha

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1583

Location: 1031 Cobblestone Way Watkinsville GA.

Receiving Stream & Watershed Name: Unnamed tributary to McNutt Creek

Outfall Type: Direct - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

---

---

---

---

---

---

N33°54'11.57301" - W83°27'54.78995"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number:                     

Location: 1380 Hollow Creek Ln. Watkinsville GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Indirect Ditch

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color:                                      Odor:                                     

Floatables (includes oil sheen, suds, & sewage):                                     

Biological Indicators (algae, emergent vegetation, etc.):                                     

Other:                                     

## D. Lab Analysis Results

pH:                                     

Conductivity:                                     

☒ Surfactants:                                     

Ammonia:                                     

Turbidity:                                     

☒ Fluoride:                                     

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID:                                     

Results:                                     

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'56, 70318"-W83°28'27.42808"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1474

Location: 1150 Laurel Pointe Watkinsville GA.

Receiving Stream & Watershed Name: Barber Creek

Outfall Type: Direct - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'59.89090"-W83°28'46.11190"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1467

Location: Bent Creek Rd. Watkinsville GA.

Receiving Stream & Watershed Name: Ditch

Outfall Type: Direct - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'54.27168"-W83°28'41.20288"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1478

Location: 1251 Bent Creek Rd. Watkinsville GA.

Receiving Stream & Watershed Name: Ditch

Outfall Type: N/A

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°53'52.65377"-W83°28'37.78669"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1481  
Location: 1281 Bent Creek Rd. Watkinsville GA.  
Receiving Stream & Watershed Name: yard  
Outfall Type: Indirect - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_  
Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_  
Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_  
Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_ Conductivity: \_\_\_\_\_  
☒ Surfactants: \_\_\_\_\_ Ammonia: \_\_\_\_\_  
Turbidity: \_\_\_\_\_ ☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_  
Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°53'46.58643" - W83°28'24.81179"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1484

Location: 1041 Laurel Springs Ct. Watkinsville GA.

Receiving Stream & Watershed Name: Pitch

Outfall Type: Indirect - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°53'45.32618"-W83°28'30.22562"

# **DRY WEATHER OUTFALL INSPECTION CHECKLIST**

Date: 3-30-2022

Inspector(s): William Rhodes

## **A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## **B. Outfall Location/Description**

ID Number: 1487  
Location: 1381 Bent Creek Rd. Watkinsville GA.  
Receiving Stream & Watershed Name: Ditch  
Outfall Type: Indirect - Metal

## **C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## **D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## **E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## **Notes/Follow-Up**

---

---

---

---

---

N33°55'28.59101"-W83°32'49.42624"

## DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 533

Location: 1021 Planters Ridge Dr. Bogart GA

Receiving Stream & Watershed Name: Unamed tributary to McWitt Creek

Outfall Type: Indirect - Ditch

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°55'33.65578"-W83°32'36.21977"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 534

Location: 1101 Planters Trail Bogart GA.

Receiving Stream & Watershed Name: Unnamed tributary to McNutt Creek

Outfall Type: Indirect - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°55'36.38727" - W83°32'31.79903"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 568

Location: 1030 Quail Ridge Way Bogart GA.

Receiving Stream & Watershed Name: Unnamed tributary to McNitt Creek

Outfall Type: Indirect - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°55'32.93542" - W83°32'31.89083"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-30-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 572

Location: 1131 Planters Trail Bogart GA.

Receiving Stream & Watershed Name: Unnamed Tributary to McNutt Creek

Outfall Type: Indirect - Metal

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'47.45322" - W83°27'47.91344"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1492

Location: 1061 Crooked Creek Rd. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'41.38915" - W83°27'46.87277"

## DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1503

Location: 1060 Brookwood Dr. Watkinsville, GA. / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch

Outfall Type: Direct - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'35.17974" - W83°28'1.08437"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1495

Location: 1221 Crooked Creek Rd. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch

Outfall Type: Direct - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°53'38.12258"-W83°27'55.18190"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1506

Location: 1140 Brookwood Dr. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch - Ditch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N 33°53'31.35937" - W 83°27'58.90699"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 8-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1508

Location: 1201 Old Farm Rd. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch - Pitch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°53'27.30075"-W83°27'57.25730"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1513

Location: 1130 Old Farm Rd. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'35.00004"-W83°28'5.36627"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1518

Location: 1251 Crooked Creek Rd. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'45.53037" W83°27'52.65001"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1519

Location: 1091 Crooked Creek Rd. Watkinsville, GA / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°53'49.13974" - W83°27'57.63210"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1022

Location: 1541 Crooked Creek Rd. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Yard / Parker Branch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

N33°53'45.84875" - W83°28'2.44386"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1026

Location: 1471 Crooked Creek Rd., Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Park Branch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_

Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°53'39.07565" - W83°27'59.91528"

# DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

## A. Confirm the Following Items Prior to Inspection

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

## B. Outfall Location/Description

ID Number: 1029

Location: 1201 Crooked Creek Rd. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Yard / Parker Branch

Outfall Type: Indirect - Concrete

## C. Visual Observations

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

## D. Lab Analysis Results

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

X Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

X Fluoride: \_\_\_\_\_

## E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

## Notes/Follow-Up

---

---

---

---

---

N33°53'40.95241"-W83°28'1.05399"

## DRY WEATHER OUTFALL INSPECTION CHECKLIST

Date: 3-22-2022

Inspector(s): William Rhodes

**A. Confirm the Following Items Prior to Inspection**

- ☒ Dry Weather (no rain for 72 hours)  
☐ Proper Sampling Bottles / Sharpie for Labeling

**B. Outfall Location/Description**

ID Number: 1019

Location: 1011 Crooked Creek Ct. Watkinsville GA. / Brookwood Estates

Receiving Stream & Watershed Name: Parker Branch

Outfall Type: Indirect - Concrete

**C. Visual Observations**

Dry Weather Flow Observed? ☒ No ☐ Yes (if yes, complete sections C, D & E below)

Color: \_\_\_\_\_ Odor: \_\_\_\_\_

Floatables (includes oil sheen, suds, & sewage): \_\_\_\_\_

Biological Indicators (algae, emergent vegetation, etc.): \_\_\_\_\_

Other: \_\_\_\_\_

**D. Lab Analysis Results**

pH: \_\_\_\_\_

Conductivity: \_\_\_\_\_

☒ Surfactants: \_\_\_\_\_

Ammonia: \_\_\_\_\_

Turbidity: \_\_\_\_\_

☒ Fluoride: \_\_\_\_\_

**E. Lab Analysis for E. Coli (\*if sewage contamination suspected/indicated)**

Sample ID: \_\_\_\_\_

Results: \_\_\_\_\_

**Notes/Follow-Up**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_