

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'43.53665"-W83°22'56.04439"

Location: 2060 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'44.29408"-W83°22'56.47280"

Location: 2071 Simonton Bridge Rd. Watkinsville GA

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'45.07274"-W83°22'56.45457"

Location: 2081 Simenton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simenton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'45.86627"-W83°22'56.52777"

Location: 2101 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'49.69046"-W83°22'54.94444"

Location: 2100 Simonton Bridge Rd. Watkinville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'10.81190"-W83°22'45.46574"

Location: 2321 Simonton Bridge Rd. Watkinsonville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'9, 24729"-W83°22'46.04863"

Location: 2330 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'7.73635"-W83°22'46.9223"

Location: 2330B Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'6.19894"-W83°22'47.33398"

Location: 2300 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-16-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'6.46733"-W83°22'47.85279"

Location: 1051 Grace Ln. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	