

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'14.45825"-W83°23'26.76710"

Location: 1565 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'20.38769" - W83°23'16.57484"

Location: 1651 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / ☒ No	
Vegetation maintained to capture sediment	Yes / ☒ No	
Debris (litter, branches, brush, etc.)	Yes / ☒ No	
Excessive siltation buildup	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes / ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N/33°52'24.08543"-W83°23'9.13246"

Location: 1800 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'25.26738"-W83°23'6.86684"

Location: 1820 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'28.43035" - W83°23'1.29858"

Location: 1901 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'28.81199" - W83°23'0.71914"

Location: 1969 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'21.66642"-W83°22'57.54735"

Location: 1940 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'33.04021"-W83°22'56.52392"

Location: 1960 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'35.18824"-W83°22'56.01365"

Location: 1971 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'36.96740"-W83°22'55.59708"

Location: 2001 Simonton Bridge Rd. Watkinsville Rd.

Ditch Footage: 17,952 ft. Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'37.82026"-W83°22'55.67217

Location: 2011 Simonton Bridge Rd. Watkinsville Rd.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'40.03216"-W 83°22'55.92663

Location: 2031 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'41.45568"-W83°22'55.54759,

Location: 2040 Simonton Bridge Rd. Watkinsville Rd.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-15-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'41.02312"-W83°22'56.14489"

Location: 2033 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	