

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'21.89896"-W83°32'33.37357"

Location: 1080 Kreneland Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'22.48847"-W83°32'29.28442"

Location: 1020 Percy Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'22.60749"-W83°32'29.32906"

Location: 1021 Derby Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <u>No</u>	
"No dumping" educational marker	Yes / <u>No</u>	
Trash or debris at inlet opening	Yes / <u>No</u>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <u>No</u>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <u>No</u>	
Pipes (roots, damaged, flow impeded)	Yes / <u>No</u>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'29.07083"-W83°32'24.00534"

Location: 1110 Derby Ln. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'29.03544" - W83°32'24.40189"

Location: 1101 Derby Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'32.19095" - W83°32'21.34533"

Location: 1140 Percy Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'32.29986"-W83°32'21.70196"

Location: 1151 Derby Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'34.57254"-W83°32'19.09323"

Location: 1170 Perley Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'34.91677"-W83°32'19.38465"

Location: 1181 Derby Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'36.63846"-W83°32'14.91415"

Location: 2000 Percy Ln, Watkinville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'36.85046"-W83°32'15.22052"

Location: 2001 Derby Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'39.80631"-W83°32'18.85575"

Location: 2190 Keeneland Dr. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'35.31291"-W83°32'13.67015"

Location: 1253 Keeneland Dr. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'35.43069"-W83°32'13.35665"

Location: 1240 Keeneland Dr. Watkinsonville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'32.97535"-W83°32'13.61703"

Location: 1253 Keeneland Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'32.88118"-W83°32'13.4322"

Location: 2110 Keeneland Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'30.03712" - W83°32'15.78572"

Location: 2081 Keeneland Dr. Watkinsonville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'29.97808"-W83°32'15.66208"

Location: 2080 Keeneland Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'26.83548" - W83°32'18.42007"

Location: 2041 Keeneland Dr. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'26.82387"-W83°32'18.35623"

Location: 2040 Keeneland Dr. Walthamville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'19.77722"-W83°32'24.25946"

Location: 1151 Keene land Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'19.54655"-W83°32'24.19048"

Location: 1130 Keeneland Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'17.73044"-W83°32'26.06247"

Location: 1010 Keeneland Dr. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'11.55244"-W83°32'30.97039"

Location: 1051 Keeneland Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'11.45554"-W83°32'30.85725"

Location: 1030 Keeneland Dr. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'17.79018"-W83°32'26.39595"

Location: 10103 Keeneland Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 3-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'17.59284" - W83°32'26.63808"

Location: 1111 Keene Land Dr. Watkinsonville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	