

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'34.58831"-W83°33'44.25920"

Location: 2361 Dials Mill Rd, Statham, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Culvert

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'36.25083"-W83°33.39.95384"

Location: 2304 Dials Mill Rd. Statham GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'40.69182"-W83°33'32.16910"

Location: 2526 Dials Mill Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'43.56499"-W83°33'30.70851"

Location: 2521 Dials Mill Rd, Statham GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'45.15935"-W83°33'29.99336"

Location: 2521B Dials Mill Rd, Statham GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'46.63552"-W83°33'29.44931"

Location: 2561 Dials Mill Rd, Statham GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'47.33154"-W83°23'29.16610"

Location: 2561 B Dials Mill Rd. Statham GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'45.46643" - W83°33'28.14558"

Location: 1567 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'43.50363" - W83°33'22.80139"

Location: 1698 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'41.72109"-W83°33'19.50036"Location: 1571 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'41.95621" - W83°33'19.07506"

Location: 1610 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'40.81759"-W83°33'17.22390"

Location: 1551 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'40.49280"-W83°33'16.41064"

Location: 1551 B Aiken Rd. Bogart GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'39.40543" - W83°33'14.17280"Location: 1521 Aiken Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'38.57588"-W83°33'12.00812"

Location: 1521 C Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N 33° 56' 38.30422" - W 83° 33' 11.30607"

Location: 1481 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'37.46693"-W83°33'8.35622"

Location: 1470 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N133°56'35.72846"-W83°33'3.33285"Location: 1420 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'35.22" W83°33'1.36299"Location: 1402 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'34.86608"-W83°32'59.56283"Location: 1390 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'34.67060" - W83°32'58.47050"

Location: 1382 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'34.55172" - W83°32'57.27570"

Location: 1370 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'34.43449"-W83°32'56.14660"Location: 1360 A'Ken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'34.23624" - W83°32'54.46646"

Location: 1352 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'34.13602"-W83°32'53.00180"

Location: 1340 Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'33.98353"-W83°32'52.39683"Location: 1342 A.Ken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'33.66391"-W83°32'53.40603"Location: 1340 B Aiken Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'30.49444"- W83°33'12.08720"

Location: 2011 Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'29.69132"-W83°33'12.12662"

Location: 1991 Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'28.46795"-W83°33'11.89680"

Location: 1991B Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'28.42652"-W83°33'12.03348"Location: 1991 C Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N 33° 56' 26, 93801" - W 83° 33' 11, 85752"Location: 1970 Pete Dicken Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'37.35246"-W83°23'4.95482"Location: 2120 Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'38.42505"-W83°33'2.82537"

Location: 2140 Pete Dickens Rd. Bogat GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'38.49582" - W83°33'2.39698"Location: 2140B Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N133°56'39.58096" - W83°33'0.35359"

Location: 2160 Pete Dickens Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33° 56' 39.85548" - W83° 32' 59.62506"

Location: 2170 Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'40.34176"-W83°32'58.76970"Location: 2180 Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'40.97059"-W83°32'57.13162"Location: 2190 Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'41.35445"- W83°32'56.34708"Location: 2200 Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'41.84608"-W83°32'55.29622"Location: 2210 Pete Dickens Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST*Culvert*Date: 1-11-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°56'41.15524"- W83°32'56.77054"Location: 2190B Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-11-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°56'43.26921" - W83°32'52.39462"

Location: 2240 Pete Dickens Rd, Bagart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	