

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'45.98413"-W83°28'17.69589"

Location: 1000 Grayson Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Culvert

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'48.74602"-W83°28'15.17758"

Location: 1036 Grayson Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'53.66211"-W83°28'11.09541"

Location: 1070 Grayson Ln. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°53'56.03763"-W83°28'11.29018"Location: 1010 Echo Brook Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rindes

Location/Description

ID #: N33°53'59.82785"-W83°28'14.11606"

Location: 1071 Echo Brook trl, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'0.33194" - W83°28'15.02029"

Location: 1071B Echo Brook Rd, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'0.49446"-W83°28'15.59138"

Location: 1071C Echo Brook trl/Debi Ct. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'59.82756" - W83°28'16.15207"

Location: 1071D Echo Brook trl. ~~RR~~ Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'0.39635"-W83°23'16.10825"

Location: 1010 Debi Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-2-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°54'2.14495"-W83°28'17.83001"Location: 1100 Echo Brook Trail Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'2.34313"-W83°28'19.32631"

Location: 1121 Echo Brook Trail Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Spillway

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'59.27054"-W83°28'9.52342"

Location: 1020 Deni Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'57.03" W83°28'5.54715"

Location: 1160 Grayson Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'56.99771"-W83°28'5.31382"

Location: 1160B Grayson Ln Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°53'57.12017"-W83°28'3.23906"Location: 1160 C Grayson Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'58.71036"-W83°28'1.31755"

Location: 1221 Grayson Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'2.63265"-W83°27'56.68754"

Location: 1051 Old Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'2.88620"-W83°27'56.10928"

Location: 1051B Old Hodges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°54'2.20957"-W83°27'55.18041"

Location: 1070 Old Hedges Mill Rd. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33° 54' 0.66748" - W83° 27' 54.70663"

Location: 1051 Old Hodges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'59.15876"-W83°27'53.63878"

Location: 1030 Old Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodeLocation/DescriptionID #: N33°53'57.28350"-W83°27'53.63059"Location: 1011 Old Hodges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°53'57.33977"-W83°27'53.21541"Location: 2801 Hodges Mill Rd, Watkinsville, GA,

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'59.60457" - W83°27'48.09229"Location: 2833 Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'57.91548"-W83°27'47.05192"Location: 2835 Hodges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'57.85910"-W83°27'47.59273"Location: 2899 Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

CATCH BASIN INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'57.28540" - W83°27'48.67320"Location: 2813 Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'56.98077" - W83°27'49.86462"Location: 2805 Hodges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DITCH INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'58.30776"-W83°27'49.12976"

Location: 28338 Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Vegetation maintained to capture sediment	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Excessive siltation buildup	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input type="radio"/> No <input checked="" type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'56.42463"-W83°27'51.93368"Location: 2801 Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Date: 1-7-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'56.20931"-W83°27'51.87353"

Location: 2805 B Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'55.37898"-W83°27'54.22699"Location: 2861 Hodges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 1-7-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 53' 55.37481" - W 83° 27' 53.80583"Location: 2789 Hedges Mill Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	