

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'32.17123"-W83°22'10.20900"

Location: 1014 Rossiter Ct. Watkinsville GA.

Ditch Footage: 162 ft.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes/No	
Vegetation maintained to capture sediment	Yes/No	
Debris (litter, branches, brush, etc.)	Yes/No	
Excessive siltation buildup	Yes/No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes/No	
Pipes/Cross Culverts (clogged or damaged)	Yes/No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'28.74823"-W83°22'7.29060"

Location: 1031 Rossiter Ct. Watkinsville GA.

Ditch Footage: 319 ft.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes/ ☒ No	
Vegetation maintained to capture sediment	Yes/ ☒ No	
Debris (litter, branches, brush, etc.)	Yes/ ☒ No	
Excessive siltation buildup	Yes/ ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes/ ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes/ ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'27.84823"-W83°22'6.77300"

Location: 1052 Rossiter Ct. Watkinsville GA.

Ditch Footage: 502 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes/No	
Vegetation maintained to capture sediment	Yes/No	
Debris (litter, branches, brush, etc.)	Yes/No	
Excessive siltation buildup	Yes/No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes/No	
Pipes/Cross Culverts (clogged or damaged)	Yes/No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'29.46080"-W83°22'4.34811"

Location: 1031B Rossiter Ct. Watkinsville GA.

Ditch Footage: 369 ft.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'27.16318"-W83°22'3.66072"

Location: 1060 Rossiter Ct. Watkinsville GA.

Ditch Footage: 100 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'27.02117"-W83°22'2.09790"

Location: 1060B Rossiter Ct. Watkinsville GA.

Ditch Footage: 115 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'26.53686"-W83°21'58.80059"

Location: 1080 Rossiter Ct. Watkinsville GA.

Ditch Footage: 252 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'27.02620"-W83°22'1.18446"
Location: 1010 Rossiter Terr. Watkinsville GA.

Ditch Footage: 500 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / ☒ No	
Vegetation maintained to capture sediment	Yes / ☒ No	
Debris (litter, branches, brush, etc.)	Yes / ☒ No	
Excessive siltation buildup	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes / ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'30.13228"-W83°22'2.84275"

Location: 1010 B Rossiter Terr. Watkinsville GA.

Ditch Footage: 298 ft.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / ☒ No	
Vegetation maintained to capture sediment	Yes / ☒ No	
Debris (litter, branches, brush, etc.)	Yes / ☒ No	
Excessive siltation buildup	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes / ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'30.86321"-W83°22'2.34673"
Location: 1021 N. Rossiter Terr. Watkinsville GA.

Ditch Footage: 167 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'31.08478"-W83°22'2.18988"

Location: 1021 B N. Rossiter Terr. Watkinsville GA.

Ditch Footage: 36 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

Culvert

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'33.00334"-W83°21'59.49261"

Location: 1041 N. Rossiter Terr.

Ditch Footage: 303 ft.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'33.06404"-W83°21'59.22876"
Location: 1041B N. Rossiter Terr. Watkinsville GA.

Ditch Footage: 109 ft.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'30.59481"-W83°22'2.27777"
Location: 1010C N. Rossiter Terr. Watkinsville GA.

Ditch Footage: 56 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

To Private Gate

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'24.33835"-W83°22'5.76216"
Location: 15. Rossiter Terr. Watkinsville GA.

Ditch Footage: 305 ft.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

To Private Gate

DITCH INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'24.24552"-W83°22'5.71792"

Location: 2 S. Rossiter Terr. Watkinsville GA.

Ditch Footage: 305 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

CATCH BASIN INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'26.08000"-W83°21'54.41409"

Location: 1079 Rossiter Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / ☒ No	
"No dumping" educational marker	Yes / ☒ No	
Trash or debris at inlet opening	Yes / ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes (roots, damaged, flow impeded)	Yes / ☒ No	

CATCH BASIN INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'25.73517"-W83°21'54.56465"

Location: 1080B Rossiter Ct. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☐ No ☒	
"No dumping" educational marker	Yes ☐ No ☒	
Trash or debris at inlet opening	Yes ☐ No ☒	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☐ No ☒	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☐ No ☒	
Pipes (roots, damaged, flow impeded)	Yes ☐ No ☒	

CATCH BASIN INSPECTION CHECKLIST

Date: 1-28-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'25.51016"-W83°21'53.97234"

Location: 1098 Rossiter Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☐ No ☒	
"No dumping" educational marker	Yes ☐ No ☒	
Trash or debris at inlet opening	Yes ☐ No ☒	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☐ No ☒	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☐ No ☒	
Pipes (roots, damaged, flow impeded)	Yes ☐ No ☒	