

Spillway

DITCH INSPECTION CHECKLIST

Date: 2-10-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'44.38755"-W83°26'58.65604"

Location: 1033 Cliff Dawson Rd, Watkinsville GA.

Ditch footage: 156 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes/No	
Vegetation maintained to capture sediment	Yes/No	
Debris (litter, branches, brush, etc.)	Yes/No	
Excessive siltation buildup	Yes/No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes/No	
Pipes/Cross Culverts (clogged or damaged)	Yes/No	

Culvert

DITCH INSPECTION CHECKLIST

Date: 2-10-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'47.40535"-W83°26'57.05574"

Location: 1080 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 263 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <u>No</u>	
Vegetation maintained to capture sediment	Yes / <u>No</u>	
Debris (litter, branches, brush, etc.)	Yes / <u>No</u>	
Excessive siltation buildup	Yes / <u>No</u>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <u>No</u>	
Pipes/Cross Culverts (clogged or damaged)	Yes / <u>No</u>	

DI

CATCH BASIN INSPECTION CHECKLIST

Date: 2-10-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'45.91649"-W83°26'58.19805"Location: 1047 Cliff Dawson Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-10-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'47.58479"-W83°26'57.40855"

Location: 1061 Cliff Dawson Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes ☒ No	
"No dumping" educational marker	Yes ☒ No	
Trash or debris at inlet opening	Yes ☒ No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes (roots, damaged, flow impeded)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-10-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'50.38489"-W83°26'55.40262"

Location: 1112 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 250 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-10-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'50.58317"-W83°26'55.83896"

Location: 1101 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 136 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-10-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'52.89040"-W83°26'54.48773"

Location: 1131 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 252 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / ☒ No	
Vegetation maintained to capture sediment	Yes / ☒ No	
Debris (litter, branches, brush, etc.)	Yes / ☒ No	
Excessive siltation buildup	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes / ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-10-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'54.4

Location: 1150 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 421 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-10-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'54.70628"-W83°26'53.41259"

Location: 1130 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 184 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	