

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
2/25/2022	1011 Stonebridge Pkwy	Needs grouting		14858	7/5/2022
	1120 Nona Drive	Need to replace lid		14263	3/2/2022

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'20.00035"-W83°26'7.11663"

Location: 1011 Stonebridge pkwy, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	Needs Grouting
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request												
14858	Road Department	Michael Weathers		2/25/2022	6:30 AM												
Location of Request																	
1011 Stonebridge Pkwy																	
Task	Date Completed																
Catch Basin Repair	7/5/2022																
Action for Task	Date of Action																
inspected catch basin, will be repaired during	7/5/2022																
<table border="1"> <thead> <tr> <th>Employee Hours and Cost</th> <th># of Employees</th> <th>Combined Hours</th> <th>Cost of Action</th> </tr> </thead> <tbody> <tr> <td></td> <td>4</td> <td>4.00</td> <td></td> </tr> </tbody> </table>						Employee Hours and Cost	# of Employees	Combined Hours	Cost of Action		4	4.00					
Employee Hours and Cost	# of Employees	Combined Hours	Cost of Action														
	4	4.00															
<u>Subcontractor Hours and Cost</u>																	
<table border="1"> <thead> <tr> <th>Equipment Hours and Cost</th> <th>Equipment</th> <th>Hours</th> <th>Equip Cost</th> </tr> </thead> <tbody> <tr> <td></td> <td>G489 FORD</td> <td>1.00</td> <td></td> </tr> <tr> <td></td> <td>G771</td> <td>1.00</td> <td></td> </tr> </tbody> </table>						Equipment Hours and Cost	Equipment	Hours	Equip Cost		G489 FORD	1.00			G771	1.00	
Equipment Hours and Cost	Equipment	Hours	Equip Cost														
	G489 FORD	1.00															
	G771	1.00															
<u>Materials Cost</u>																	
<table> <tr> <td>Employee Costs for this Task:</td> <td>\$0.00</td> </tr> <tr> <td>Subcontractor Costs for this Task:</td> <td>\$0.00</td> </tr> <tr> <td>Equipment Costs for this Task:</td> <td>\$0.00</td> </tr> <tr> <td>Materials Costs for this Task:</td> <td>\$0.00</td> </tr> </table>						Employee Costs for this Task:	\$0.00	Subcontractor Costs for this Task:	\$0.00	Equipment Costs for this Task:	\$0.00	Materials Costs for this Task:	\$0.00				
Employee Costs for this Task:	\$0.00																
Subcontractor Costs for this Task:	\$0.00																
Equipment Costs for this Task:	\$0.00																
Materials Costs for this Task:	\$0.00																
<table border="1"> <tr> <td>Total All Employee Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Subcontractor Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Equipment Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Materials Costs:</td> <td>\$0.00</td> </tr> <tr> <td>GRAND TOTAL:</td> <td>\$0.00</td> </tr> </table>						Total All Employee Costs:	\$0.00	Total All Subcontractor Costs:	\$0.00	Total All Equipment Costs:	\$0.00	Total All Materials Costs:	\$0.00	GRAND TOTAL:	\$0.00		
Total All Employee Costs:	\$0.00																
Total All Subcontractor Costs:	\$0.00																
Total All Equipment Costs:	\$0.00																
Total All Materials Costs:	\$0.00																
GRAND TOTAL:	\$0.00																

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'19.58548"-W83°26'6.57474"

Location: 1010 Stonebridge Pkwy. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

GI Culvert

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'27.16494" - W83°26'1.08386"Location: 1031 Stonebridge PKwy. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'27.22008"-W83°26'1.09905"

Location: 111 Stonebridge Pkwy. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'26.97982"-W83°25'56.42816"

Location: 1110 Stonebridge Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'27.16620" - W83°25'56.16489"

Location: 1100 Stonebridge Rd. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'23.32211" - W83°25'56.40215"

Location: 1060 Stonebridge Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'23.27295"-W83°25'56.05860"

Location: 1070 Stonebridge Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'21.33422"- W83°25'56.44303"

Location: 1060B Stonebridge Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'21.04901"- W83°25'56.27554"

Location: 1011 Stonebridge Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'20.72104"-W83°25'59.48154"

Location: 1020 Stonebridge Ct. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input type="radio"/> No <input checked="" type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33° 52' 23, 34021" - W 83° 25' 49, 46873"

Location: 1160 Stoneridge Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'23.54784" - W83°25'49.73779"

Location: 1181 Stonebridge Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'25.88290"-W83°25'51.84904"

Location: 1030 Stonebridge Cir. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'25.62040" - W83°25'51.94771"

Location: 1031 Stonebridge Cir. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST*Square Top*Date: 2-25-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'31.44084" - W83°25'54.32124"Location: 1150 Stonebridge PKwy Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'31.74479"-W83°25'54.85532"

Location: 1113 Stonebridge PKWY Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'31.08172"-W83°25'46.88146"

Location: 1051 Latham Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'31.47286"-W83°25'46.65995"

Location: 1001 Latham Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST*Square Top*Date: 2-25-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33° 52'34.95888" - W83°25'37.83485"Location: 1031 Daniel Ct, Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'40.41142" - W83°25'45.54475"

Location: 1180 Latham Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'40.15348" - W83°25'45.75902"

Location: 1171 Latham Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'38.79965"-W83°25'49.58965"

Location: 1040 Queen Anne Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'40.72489"- W83°25'46.07849"

Location: 1171B Latham Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'41.11987"- W83°25'46.30679"

Location: 1201 Latham Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'47.22625" - W83°25'50.50336"

Location: 1230 Latham Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 205-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'41.15544"-W83°25'55.66739"

Location: 1291 Latham Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'41.25716"- W83°25'56.17689"

Location: 1291B Latham Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'37.39566" - W83°25'56.17629"

Location: 1161 Stonebridge Pkwy. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'37.39637"-W83°25'56.21131"

Location: 1299 Stonebridge PKWY Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST*Square Top
GI*Date: 2-25-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'28.40447"-W83°26'22.30889"Location: 1201 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'28.15024"-W83°26'22.35543"

Location: 1200 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'28.88483"-W83°26'23.87931"

Location: 1191 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33° 54' 28.79223" - W 83° 26' 26.83311"

Location: 1171 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'28.03556" - W83°26'27.62024"

Location: 1160 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'28.22348" - W83°26'27.20095"

Location: 1341 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'27.77471"- W83°26'31.50711"

Location: 1141 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'27.40695" - W83°26'31.54171"

Location: 1140 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'19.53419"-W83°26'34.30779"

Location: 1040 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'16, 31801" - W83°26'32.54737"

Location: 1001 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'16.68989"-W83°26'32.42226"

Location: 1010 Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'5.72689"- W83°26'32.93248"

Location: 1141 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'5.52723"-W83°26'32.43667"

Location: 1120 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	<input checked="" type="radio"/> Yes / <input type="radio"/> No	<i>Need to replace Lid</i>
"No dumping" educational marker	<input type="radio"/> Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	<input type="radio"/> Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	<input type="radio"/> Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	<input type="radio"/> Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	<input type="radio"/> Yes / <input checked="" type="radio"/> No	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14263	Road Department	Michael Weathers		2/25/2022	7:30 AM

Location of Request

1120 Nona Drive

Task

Catch Basin Repair

Date Completed

3/2/2022

Date of Action

3/2/2022

Action for Task

inspected top, will replace at later date, not af

Employee Hours and Cost
of Employees
Combined Hours
Cost of Action

4 2.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

G489 FORD 0.50

G771 0.50

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

CATCH BASIN INSPECTION CHECKLIST*Square Top
GI*Date: 2-25-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'2.52843"-W83°26'30.30973"Location: 1101 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

GI

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'2.87751"-W83°26'30.21321"Location: 1090 Nona Dr. Watkingsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhoads

Location/Description

GPS Point Name: N33°54'7.14371"-W83°26'28.87041"

Location: 1041 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'6.21516" - W83°26'28.73545"

Location: 1060 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input type="radio"/> No <input checked="" type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'10.89146" - W83°26'29.92701"

Location: 1040 Scott Terrace Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'12.02292"-W83°26'28.94414"

Location: 1050 Scott Terrace Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'12.28010" - W83°26'29.01860"

Location: 1031 Scott Terrace, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Spillway

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'13.00673" - W83°26'27.64434"

Location: 1050B Scott Terrace, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33° 54' 11.18575" - W 83° 26' 30.16744"

Location: 1190 Nana Dr. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'10.77309"- W83°26'30.26365"

Location: 1020 Scott Terrace Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'10.80200" - W83°26'32.46321"

Location: 1190 B Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'17.24367" - W83°26'31.27977"

Location: 1240 Nana Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST*Square Top*Date: 2-25-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'17.39071"-W83°26'31.53085"Location: 1010B Beverly Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'18.07774" - W83°26'29.79910"

Location: 1260 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

JB

CATCH BASIN INSPECTION CHECKLISTDate: 2-25-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'18.05855"- W83°26'30.10622"Location: 1260 Nana Dr. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input type="radio"/> No <input checked="" type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'18.35817" - W83°26'29.99943"

Location: 1251 Nana Dr. Watkinsville, GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'19.02834"-W83°26'26.70300"

Location: 1270 Nana Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input type="radio"/> No <input checked="" type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'19.30463"-W83°26'27.02639"

Location: 1261 Nana Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'19.74483"-W83°26'24.45726"

Location: 1010 Sylvia Ct. Watkinsville Ga.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'20.07267"-W83°26'24.30394"

Location: 1310 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'18.77187"-W83°26'22.90960"

Location: 1030 Sylvia Ct, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'20.64538"-W83°26'25.54235"

Location: 1310B Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'20.69298"-W83°26'25.96669"

Location: 1291 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'22.64854"-W83°26'30.70282"

Location: 1031 Chris Ct. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'26.58509"-W83°26'27.07183"

Location: 1370 Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-25-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'26.51507"-W83°26'27.16386"

Location: 1370 B Nona Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
"No dumping" educational marker	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Trash or debris at inlet opening	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	