

*Square Top*

**CATCH BASIN INSPECTION CHECKLIST**

Date: 2-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'16.19800" - W83°31'48.69078"

Location: 1071 Cantrell Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'16.21332"-W83°31'48.33397"

Location: 1050 Cantrell Ln. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

# Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'20.51530"-W83°31'47.87221"

Location: 1140 Wellington Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'20.55721" - W83°31'47.50216"

Location: 2000 Cantrell Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

*Square Top*

**CATCH BASIN INSPECTION CHECKLIST**

Date: 2-24-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33°55'24.49181" - W 83°31'45.35606"

Location: 2030 Cantrell Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'24.74892" - W83°31'45.63490"

Location: 2021 Contrell Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

# CATCH BASIN INSPECTION CHECKLIST

Square Top

Date: 2-24-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N 33° 55' 28.17730" - W 83° 31' 42.43248"

Location: 2070 Cantrell Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'25.50317"-W83°31'45.66700"

Location: 2070B Cantrell Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'25.24508" - W83°31'45.79618"

Location: 1001 Nash Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'26.36188"-W83°31'51.11879"

Location: 1050 Nash Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'26.23437"-W83°31'51.12748"

Location: 1061 Nash Ct. Wadkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

# 5quare Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-29-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'20.29129"-W83°31'47.79437"

Location: 1101 Cantrell Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'19.97571"-W83°31'47.85094"

Location: 1091 Cantrell Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'13.07826"-W83°31'53.00135"

Location: 1031 Wellington Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

**CATCH BASIN INSPECTION CHECKLIST***Square Top*Date: 2-24-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°55'12.80595"-W83°31'52.73436"Location: 1040 Wellington Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°55'12,67195"-W83°31'52.87103"

Location: 1040 B Wellington Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

# *Square Top*

## **CATCH BASIN INSPECTION CHECKLIST**

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'9.84008"-W83°28'1.01257"

Location: 1011 Fox Glenn Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°34'9.90827"-W83°28'1.09677"

Location: 1011B Fox Glen Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'5.88935" - W83°28'6.80672"

Location: 1251 Hollow Creek Ln, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-28-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'5.60219"-W83°28'6.69178"

Location: 1251B Hollow Creek Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-24-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'8.70293"-W83°28'10.96984"

Location: 1200 Hollow Creek Ln. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	