

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
2/23/2022	1021 West View Court	Pipe is clogged up	12	14857	7/5/2022
	1100 Paul Ridge Road	Needs to be cleaned out	1	14276	3/3/2022

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'42.77959"-W83°28'49.85482"

Location: 1115 Fieldstone Rd. Wetherlyville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Square Top

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'42.82104" - W83°28'50.91171"

Location: 1110 Fieldstone Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'37.40279"-W83°29'4.61814"

Location: 1010 Sage Field Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input type="radio"/> No <input checked="" type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'38.05530" - W83°29'4.90727"

Location: 1098 Sagfield Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'38.16947"-W83°29'4.57494"

Location: 1031 Sagfield Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'39.02946"-W83°29'6.11531"

Location: 1020 Oak Hill Ct. Watkinsville, GA.

Inspection items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'41.69793"-W83°29'2.52667"

Location: 1021 West View Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	<u>Pipe Clogged up.</u>

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14857	Road Department	Michael Weathers		2/23/2022	6:30 AM

Location of Request

1021 West View Court

Task	Date Completed
Pipe Cleaning	7/5/2022

Action for Task	Date of Action
removed 12 tons of silt and debris from end of	7/5/2022

Employee Hours and Cost	# of Employees	Combined Hours	Cost of Action
	4	16.00	

Subcontractor Hours and Cost

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	D493 DUMP TRUCK	4.00	
	D494 DUMP TRUCK	4.00	
	D878 CAT MINI EXCAVATOR	4.00	
	D948 FORD DUMP TRUCK	4.00	
	G489 FORD	4.00	

Materials Cost	Material Name	Amount Used (Units)	Measured In	Material Cost
	Silt material removed	12.00	tons	
Employee Costs for this Task:		\$0.00		
Subcontractor Costs for this Task:		\$0.00		
Equipment Costs for this Task:		\$0.00		
Materials Costs for this Task:		\$0.00		

Total All Employee Costs:	\$0.00
Total All Subcontractor Costs:	\$0.00
Total All Equipment Costs:	\$0.00
Total All Materials Costs:	\$0.00
GRAND TOTAL:	\$0.00

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'40.97846" - W83°29'0.57999"

Location: 1071 Sagefield Dr. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'40.60414"-W83°29'0.41122"

Location: 1050 Sagefield Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'36.53564"-W83°29'4.60335"

Location: 1010B Sagefield Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'28.31014"- W83°28'56.93709"

Location: 1070 Canyon Creek Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'28.29628"-W83°28'56.69871"

Location: 1081 Canyon Creek Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'27.15291" - W83°29'1.73394"

Location: 1020 W. Canyon Creek Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'27.20819"-W83°29'2.08820"

Location: 1020 B W. Canyon Creek Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'22.24100"-W83°29'2.73479"

Location: 1151 Canyon Creek Rd, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'22.59" W83°28'56.13" W 490"

Location: 1030 E. Canyon Creek Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CB

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'30.79202"-W83°28'49.77331"Location: 1060 Rosewood Trl. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <u>No</u>	
"No dumping" educational marker	Yes / <u>No</u>	
Trash or debris at inlet opening	Yes / <u>No</u>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <u>No</u>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <u>No</u>	
Pipes (roots, damaged, flow impeded)	Yes / <u>No</u>	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33° 54' 31.05233" - W 83° 28' 49.82165"

Location: 1041 Rosewood Trl. Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'25.76807"-W83°28'45.95562"

Location: 1131 Paul Ridge Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'25.96790" - W83°28'46.21120"

Location: 1100 Paul Ridge Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	<i>Need to be cleaned out</i>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14276	Road Department	Michael Weathers		2/23/2022	7:30 AM

Location of Request

1100 Paul Ridge

Task

Catch Basin Cleaning

Date Completed

3/3/2022

Action for Task

removed 1 ton of silt from basin

Date of Action

3/3/2022

Employee Hours and Cost
of Employees
Combined Hours
Cost of Action

4

4.00

Subcontractor Hours and Cost

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	D147 NEW FLAT BED	1.00	
	D493 DUMP TRUCK	1.00	
	D494 DUMP TRUCK	1.00	
	D878 CAT MINI EXCAVATOR	1.00	
	G489 FORD	1.00	

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

Square Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°34'23.61282"-W83°28'49.92072"

Location: 1150 Paul Ridge Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

5quare Top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'33.05095"-W83°28'43.10135"

Location: 1050 Paul Ridge Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Square Top

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'32.89045"-W83°28'42.75527"

Location: 1051 Paul Ridge Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST*Square Top*Date: 2-23-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'36.44446" - W83°29'21.05188"Location: 1020 Bratton Ct. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/>	

square top

CATCH BASIN INSPECTION CHECKLIST

Date: 2-23-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N 33° 54' 36.57322" - W 83° 29' 21.0897"

Location: 1020 Brockton Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	