

DITCH INSPECTION CHECKLIST

Date: 3-17-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'17.65469"-W83°22'42.20945"

Location: 2430 Simonton Bridge Rd, Watkinsville GA.

Ditch Footage: 17,952ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / ☒ No	
Vegetation maintained to capture sediment	Yes / ☒ No	
Debris (litter, branches, brush, etc.)	Yes / ☒ No	
Excessive siltation buildup	Yes / ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes / ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-17-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'21.72575"-W83°22'39.57261"

Location: 2470 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-17-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'58.94138" - W83°22'51.26542"

Location: 2201 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <u>No</u>	
Vegetation maintained to capture sediment	Yes / <u>No</u>	
Debris (litter, branches, brush, etc.)	Yes / <u>No</u>	
Excessive siltation buildup	Yes / <u>No</u>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <u>No</u>	
Pipes/Cross Culverts (clogged or damaged)	Yes / <u>No</u>	

DITCH INSPECTION CHECKLIST

Date: 3-17-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'52.21731"-W83°22'53.54680"

Location: 2150 Simonton Bridge Rd. Watkinsville GA

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 3-17-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'53.24283"-W83°22'53.34170

Location: 2151 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 17,952 ft Total of Simonton Bridge Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	