

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'16.46271"-W83°22'40.28973"

Location: 1011 Station Dr. Watkinsville GA.

Ditch Footage: 115 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'15.47512"-83°22'40.15065"

Location: 1031 Station Dr. Watkinsville GA.

Ditch Footage: 81 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'13.86954"-W83°22'40.21414"

Location: 1050 Station Pt. Watkinsville GA.

Ditch Footage: 40 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'13.64669"-W83°22'40.10566"

Location: 1050B Station Rt. Watkinsville GA.

Ditch Footage: 150 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'12.53075"-W83°22'36.59750"

Location: 1011 Victoria Crossing Watkinsville GA.

Ditch Footage: 453 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'12.91410"-W83°22'35.64794"

Location: 1041 Victoria Crossing Watkinsville GA.

Ditch Footage: 71 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'12.72148"-W83°22'35.32023"

Location: 1040 Victoria Crossing Watkinsville GA.

Ditch Footage: 215 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# Culvert

## DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

### Location/Description

ID #: N33°52'13.01525"-W83°22'33.47874"

Location: 1040B Victoria Crossing Watkinsville GA.

Ditch Footage: 168 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

Culvert

DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'13.58677"-W83°22'33.64853"

Location: 1041C Victoria Crossing Watkinsville GA.

Ditch Footage: 168 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'13.68799"-W83°22'31.29629"

Location: 1060 Victoria Crossing Watkinsville GA.

Ditch Footage: 187 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'14.09843"-W83°22'31.23674"

Location: 1061 Victoria Crossing Watkinsville GA.

Ditch Footage: 146 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'13.80703"-W83°22'28.74199"

Location: 1080 Victoria Crossing Watkinsville GA.

Ditch Footage: 186 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'14.12375"-W83°22'28.73580"

Location: 1081 Victoria Crossing WatKinsville GA.

Ditch Footage: 185 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'14.29808"-W83°22'26.31002"

Location: 1101 Victoria Crossing Watkinsville GA.

Ditch Footage: 195 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'13.70091"-W83°22'25.99197"

Location: 1100 Victoria Crossing Watkinsville GA.

Ditch Footage: 238 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'13.42572"-W83°22'25.85606"

Location: 1100 B Victoria Crossing Watkinsville GA.

Ditch Footage: 30 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'14.92236"-W83°22'23.61590"

Location: 1131 Victoria Crossing Watkinsville GA.

Ditch Footage: 210 ft

| Inspection Items                                                | Maintenance Required?                                         | Comments/Follow-up |
|-----------------------------------------------------------------|---------------------------------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'14.62060"-W83°22'22.60020"

Location: 1150 Victoria Crossing Watkinsville GA.

Ditch Footage: 277 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'14.97794"-W83°22'22.82870"

Location: 1151 Victoria Crossing Watkinsville GA.

Ditch Footage: 53 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'15.41962"-W83°22'20.88390"

Location: 1170 Victoria Crossing Watkinsville GA.

Ditch Footage: 161 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'15.73603"-W83°22'20.55542"

Location: 1171 Victoria Crossing Watkinsville GA.

Ditch Footage: 182 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Roberts

## Location/Description

ID #: N33°52'16.14111" - W83°22'18.69513"

Location: 1170B Victoria Crossing

Ditch Footage: 176 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# Culvert

## DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

### Location/Description

ID #: N33°52'16.62425"-W83°22'18.93298"

Location: 1171 B. Victoria Crossing Watkinsville GA.

Ditch Footage: 166 ft

| Inspection Items                                                | Maintenance Required? | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------|--------------------|
| Proper slope                                                    | Yes/No                |                    |
| Vegetation maintained to capture sediment                       | Yes/No                |                    |
| Debris (litter, branches, brush, etc.)                          | Yes/No                |                    |
| Excessive siltation buildup                                     | Yes/No                |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes/No                |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes/No                |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'16.84243"-W83°22'18.08239"

Location: 1191 Victoria Crossing Watkinsville GA.

Ditch Footage: 68 ft

| Inspection Items                                                | Maintenance Required?                                         | Comments/Follow-up |
|-----------------------------------------------------------------|---------------------------------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'16.99179"-W83°22'16.42777"

Location: 1190 Victoria Crossing Watkinsville GA.

Ditch Footage: 195 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'17.76501"-W83°22'15.78226"

Location: 1211 Victoria Crossing Watkinsville GA.

Ditch Footage: 192 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'17.19431"-W83°22'15.99203"

Location: 1210 Victoria Crossing Watkinsville GA.

Ditch Footage: 33 ft

| Inspection Items                                                | Maintenance Required?                                         | Comments/Follow-up |
|-----------------------------------------------------------------|---------------------------------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No <input type="radio"/> |                    |

Culvert

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'18.38251"-W83°22'13.28961"

Location: 1210B Victoria Crossing Watkinsville GA,

Ditch Footage: 217 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# Culvert

## DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

### Location/Description

ID #: N33° 52' 18.64097" - W83° 22' 13.82905"

Location: 1211 B Victoria Crossing Watkinsville GA

Ditch Footage: 189 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'19.14673"-W83°22'11.18348"

Location: 1241 Victoria Crossing Watkinsville GA.

Ditch Footage: 221 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'19.21417"-W83°22'9.89115"

Location: 1261 Victoria Crossing Watkinsville GA.

Ditch Footage: 58 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

## DITCH INSPECTION CHECKLIST

Date: 1-31-2022Inspector(s): William RhodesLocation/DescriptionID #: N33°52'18.38253" - W83°22'13.38502"Location: 1210 C Victoria Crossing Watkinville GA.Ditch Footage: 474 ft

| Inspection Items                                                | Maintenance Required?                     | Comments/Follow-up |
|-----------------------------------------------------------------|-------------------------------------------|--------------------|
| Proper slope                                                    | Yes / <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes / <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes / <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes / <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes / <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes / <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'20.34520"-W83°22'7.97361"

Location: 1431 Station Dr. Watkinsville GA.

Ditch Footage: 344 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'19.46796"-W83°22'7.01359"

Location: 1420 Station Dr. Watkinsville GA.

Ditch Footage: 64 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'18.18227"-W83°22'7.59815"

Location: 1410 Station Dr. Watkinsville GA.

Ditch Footage: 117 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'17.49502"-W83°22'8.59458"

Location: 1381 Station Dr. Watkinsville GA.

Ditch Footage: 89 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'17.66928"-W83°22'7.88825"

Location: 1390 Station Dr. Watkinsville GA.

Ditch Footage: 37 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'16.39207"-W83°22'8.87584"

Location: 1370 Station Rd. Watkinsville GA.

Ditch Footage: 120 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'15.64011"-W83°22'9.98231"

Location: 1381B Station R. Watkinsville GA.

Ditch Footage: 100 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'15.44815"-W83°22'10.97662"

Location: 1351 Station Dr. Watkinsville GA.

Ditch Footage: 277 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 1-31-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'15.18922"-W83°22'10.63132"

Location: 1360 Station Dr. Watkinsville GA.

Ditch Footage: 44 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |