

DITCH INSPECTION CHECKLIST

Culvert

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'12.39034"-W83°26'1.56160"

Location: 1649B Cliff Dawson Rd. Watkinsville Rd.

Ditch Footage: 676

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes/ ☒ No	
Vegetation maintained to capture sediment	Yes/ ☒ No	
Debris (litter, branches, brush, etc.)	Yes/ ☒ No	
Excessive siltation buildup	Yes/ ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes/ ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes/ ☒ No	

Culvert 2

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: _____

Location: 1649C Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 224 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / No	
Vegetation maintained to capture sediment	Yes / No	
Debris (litter, branches, brush, etc.)	Yes / No	
Excessive siltation buildup	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes/Cross Culverts (clogged or damaged)	Yes / No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'11.86821"-W83°26'8.44108"

Location: 1649D Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 359 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'10.45123"-W83°26'16.75556"

Location: 1463 Cliff Dawson Rd. Watkinsville Rd.

Ditch Footage: 688 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'17.76161"-W83°26'28.75973"

Location: 1401 Cliff Dawson Rd, Watkinsville GA,

Ditch Footage: 1020 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'9.02092"-W83°26'25.27378"

Location: 1449 Cliff Dawson Rd, Watkinsville GA.

Ditch Footage: 470 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'9.28102"-W83°26'24.45127"

Location: 1463 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 261 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

Culvert Opposite

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'4.96561"-W83°26'36.16957"

Location: 1061B Mass Creek Dr. Watkinsville GA.

Ditch Footage: 662 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'7.05942"-W83°26'30.44113"

Location: 14013 Cliff Dawson Rd. Watkinsville GA.

Ditch Footage: 339 ft

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'12.31335"-W83°25'39.33190"

Location: 1532 Government Station Rd. Watkinsville GA.

Ditch Footage: 12,672 ft Total for Government Station Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°53'4.62002"-W83°25'35.84608"

Location: 1401 Government Station Rd. Watkinsville GA.

Ditch Footage: 12,672 ft Total for Government Station Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'39.88632"-W83°25'32.31515"

Location: 3001 Government Station Rd. Watkinsville GA.

Ditch Footage: 12,672 ft total for Government Station Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N133°52'39.90439"-W83°25'31.82984"

Location: 1354 Government Station Rd. WatKinsville GA.

Ditch Footage: 12,672 ft Total for Government Station Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

Culvert

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'34.31313"-W83°25'31.17584"

Location: 1354 Government Station Rd. Watkinsville GA.

Ditch Footage: 12,672 ft total for Government Station Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'23.48568"-W83°25'33.20945"

Location: 1510 Experiment Station Rd. Watkinsville GA.

Ditch Footage: 12,672 ft Total for Government Station Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	

DITCH INSPECTION CHECKLIST

Date: 2-14-2022

Inspector(s): William Rhodes

Location/Description

ID #: N33°52'23.61760"-W83°25'32.62940"

Location: 1254 Government Station Rd. Watkinsville GA.

Ditch Footage: 12,672 ft Total for Government Station Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes ☒ No	
Vegetation maintained to capture sediment	Yes ☒ No	
Debris (litter, branches, brush, etc.)	Yes ☒ No	
Excessive siltation buildup	Yes ☒ No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes ☒ No	
Pipes/Cross Culverts (clogged or damaged)	Yes ☒ No	