

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'9.87911"-W83°22'57.31010"

Location: 1000 Churchill Ln. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required? | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes/ <u>No</u>        |                    |
| "No dumping" educational marker                                        | Yes/ <u>No</u>        |                    |
| Trash or debris at inlet opening                                       | Yes/ <u>No</u>        |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes/ <u>No</u>        |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes/ <u>No</u>        |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes/ <u>No</u>        |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'9.69009"-W83°22'57.43919"

Location: 1011 Churchill Ln. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'9.60418"-W83°22'58.99134"

Location: 1183 Victoria Rd. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'9.21425"-W83°22'58.84401"

Location: 1200 Victoria Rd. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'9.60536"-W83°23'0.08616"

Location: 1200B Victoria Rd. Watkinsonville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'10.60062"-W83°23'6.00591"

Location: 1000 Collinwood Ct. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'10.61068"-W83°23'5.90704"

Location: 1011 Collinwood Ct. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'10.01649"-W83°23'6.82374"

Location: 1020 Collingwood Ct. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'9.73910"-W83°23'6.54734"

Location: 1011B Collinwood Ct. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# GATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'12.61388"-W83°23'3.96195"

Location: 1020 St. James Pl. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                   | Comments/Follow-up |
|------------------------------------------------------------------------|-----------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'12.64665"-W83°23'4.16732"

Location: 1001 St. James Pl. Watkinsville GA.

| Inspection Items                                                       | Maintenance Required?                     | Comments/Follow-up |
|------------------------------------------------------------------------|-------------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes / <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes / <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes / <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes / <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes / <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes / <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'14.51608"-W83°23'19.65834"

Location: 1610 Norton Rd. Watkinsville GA.

Ditch Footage: 625 ft.

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'13.47253"-W83°23'20.92244"

Location: 1610 Simonton Bridge Rd. Watkinsville GA.

Ditch Footage: 580 ft.

| Inspection Items                                                | Maintenance Required?                     | Comments/Follow-up |
|-----------------------------------------------------------------|-------------------------------------------|--------------------|
| Proper slope                                                    | Yes / <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes / <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes / <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes / <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes / <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes / <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'8.61053"-W83°23'21.52780"

Location: 1551 Norton Rd. Watkinsville GA.

*Ditch Footage: 183 ft.*

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'7.55982"-W83°23'22.04205"

Location: 1551B Norton Rd. Watkinsville GA.

Ditch Footage: 103 ft.

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'2.45249"-W83°23'21.43001"

Location: 1550 Norton Rd, Watkinsville GA.

Ditch Footage: 51 ft

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'6.85186"-W83°23'21.64384"

Location: 1540 Norton Rd. Watkinsville GA.

Ditch Footage: 48 ft.

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°51'58.16361"-W83°23'27.28729"

Location: 1450 Norton Rd. Watkinsville GA.

*Ditch Footage: 1017 ft.*

| Inspection Items                                                | Maintenance Required?                   | Comments/Follow-up |
|-----------------------------------------------------------------|-----------------------------------------|--------------------|
| Proper slope                                                    | Yes <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes <input checked="" type="radio"/> No |                    |

# DITCH INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

ID #: N33°52'1.13649"-W83°23'25.20549"

Location: 1490 Norton Rd. Watkinsville GA.

*Ditch Footage: 297 ft*

| Inspection Items                                                | Maintenance Required?                    | Comments/Follow-up |
|-----------------------------------------------------------------|------------------------------------------|--------------------|
| Proper slope                                                    | Yes/ <input checked="" type="radio"/> No |                    |
| Vegetation maintained to capture sediment                       | Yes/ <input checked="" type="radio"/> No |                    |
| Debris (litter, branches, brush, etc.)                          | Yes/ <input checked="" type="radio"/> No |                    |
| Excessive siltation buildup                                     | Yes/ <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals) | Yes/ <input checked="" type="radio"/> No |                    |
| Pipes/Cross Culverts (clogged or damaged)                       | Yes/ <input checked="" type="radio"/> No |                    |

# CATCH BASIN INSPECTION CHECKLIST

Date: 2-7-2022

Inspector(s): William Rhodes

## Location/Description

GPS Point Name: N33°52'2.24185"-W83°23'24.52870"

Location: 1490B Norton Rd. WatNassville GA.

| Inspection Items                                                       | Maintenance Required?                     | Comments/Follow-up |
|------------------------------------------------------------------------|-------------------------------------------|--------------------|
| Structure (damaged, settled, cracked)                                  | Yes / <input checked="" type="radio"/> No |                    |
| "No dumping" educational marker                                        | Yes / <input checked="" type="radio"/> No |                    |
| Trash or debris at inlet opening                                       | Yes / <input checked="" type="radio"/> No |                    |
| Sediment (cleaning required if sediment exceeds 1/3 of the sump depth) | Yes / <input checked="" type="radio"/> No |                    |
| Contaminants or pollution (evidence of oils, grease, chemicals)        | Yes / <input checked="" type="radio"/> No |                    |
| Pipes (roots, damaged, flow impeded)                                   | Yes / <input checked="" type="radio"/> No |                    |