

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
2/2/2022	1100 Willowynd Way	Need to be cleaned out		14245	3/1/2022
	1111 Willowynd Way	Need to be cleaned out		14246	3/1/2022

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'15.70474"-W83°23'15.06918"Location: 1031 Summer Ct Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'15.67486"-W83°23'15.37477"Location: 1020 Summer Ct. W/ Kennesaw GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'17.13214"-W83°23'14.57375"Location: 1041 Summer Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'17.95654"- W83°23'15.21828"Location: 1050 Summer Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'2.96173"-W83°23'21.53059"Location: 1000 Willowynd Way, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'3.1114"-W83°23'21.56596"Location: 1011 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'2.56306"-W83°23'20.00703"Location: 1030 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'2.83772" - W83°23'19.78016"Location: 1031 Willownd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'2.81499"-W83°23'17.12017"Location: 1050 Willownd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-2-2022

Inspector(s): William Charles

Location/Description

GPS Point Name: N33°52'3.18725"-W83°23'17.48858"

Location: 1041 Willownd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DI

CATCH BASIN INSPECTION CHECKLIST

Date: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'3.42735"-W83°23'17.76709"Location: 1041B Willowynd Way Winterville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'3.60770"-W83°23'16.14191"Location: 1061 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-2-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'3.63062"-W83°23'14.77975"

Location: 1060 Willowind Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.023N 83°23'14.84775WLocation: 1071 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLIST

Date: 2-2-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'4.12992"-W83°23'12.48199"

Location: 1081 Willownd Way, Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.04109"- W83°23'10.51726"Location: 1100 Willowind Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	Need to be cleaned out
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14245	Road Department	Michael Weathers		2/2/2022	7:30 AM

Location of Request

1100 Willowynd Way

Task

Catch Basin Cleaning

Date Completed

3/1/2022

Action for Task

removed trash from inside of catch basin

Date of Action

3/1/2022

Employee Hours and Cost
of Employees
Combined Hours
Cost of Action

4 4.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

D147 NEW FLAT BED 1.00

D494 DUMP TRUCK 1.00

G489 FORD 1.00

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

Total All Employee Costs: \$0.00

Total All Subcontractor Costs: \$0.00

Total All Equipment Costs: \$0.00

Total All Materials Costs: \$0.00

GRAND TOTAL: \$0.00

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.25989"- W83°23'10.50827"Location: 1091 Willowynd Way Waltherville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.42307"-W83°23'8.84000"Location: 111 Willowind Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	<i>Need to be cleaned out</i>
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14246	Road Department	Michael Weathers		2/2/2022	7:30 AM
Location of Request					
1111 Willowynd Way					
Task	Date Completed				
Catch Basin Cleaning	3/1/2022				
Action for Task	Date of Action				
removed trash from inside of catch basin	3/1/2022				
<u>Employee Hours and Cost</u>	# of Employees	Combined Hours	Cost of Action		
	3	3.00			
<u>Subcontractor Hours and Cost</u>					
<u>Equipment Hours and Cost</u>	Equipment	Hours	Equip Cost		
	D147 NEW FLAT BED	1.00			
	D494 DUMP TRUCK	1.00			
	G489 FORD	1.00			
<u>Materials Cost</u>					
Employee Costs for this Task:	\$0.00				
Subcontractor Costs for this Task:	\$0.00				
Equipment Costs for this Task:	\$0.00				
Materials Costs for this Task:	\$0.00				
Total All Employee Costs:	\$0.00				
Total All Subcontractor Costs:	\$0.00				
Total All Equipment Costs:	\$0.00				
Total All Materials Costs:	\$0.00				
GRAND TOTAL:	\$0.00				

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.21038"-W83°23'7.88080"Location: 1110 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.49497"-W83°23'7.92459"Location: 1111B Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'2.33743" - W83°23'7.01703"Location: 1001 Willowynd Pt. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'2.45490" W83°23'7.37250"Location: 110 B Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'1.28561" - W83°23'7.00837"Location: 1040 Willowynd Pt. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.61388"-W83°23'3.50578"Location: 1130 Willowind Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.82298"-W83°23'3.47555"Location: 1141 Willowynd Way Waltherville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.69455"-W83°23'1.13070"Location: 1150 Willownd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'5.05131"- W83°23'1.18031"Location: 1161 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.92899"-W83°22'58.75452"Location: 1160B Willowynd Way, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'5.24385"-W83°22'58.73761"Location: 1181 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.74097"-W83°22'56.79289"Location: 1160 C Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'5.07514"-W83°22'56.82350"Location: 1191 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'3.82248"-W83°22'52.14239"Location: 1276 Willownd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.15471"-W83°22'52.29426"Location: 1221 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

DI
CATCH BASIN INSPECTION CHECKLIST

Date: 2-2-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°52'4.35675" - W83°22'52.32390"

Location: 1221B Willowynd Way, Watkinsville, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'3.92532"-W83°22'49.33051"Location: 1221C Willowynd Way Waltherville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.21930"-W83°22'49.43741"Location: 1241 Willowend Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'3.94671"-W83°22'47.99558"Location: 1278 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'4.24961"-W83°22'48.09515"Location: 1271 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

CATCH BASIN INSPECTION CHECKLISTDate: 2-2-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°52'3.82" W83°22'46.86557"Location: 1291 Willowynd Way Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	