

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
2/22/2022	1341 Twin Lakes Rd	Needs to be cleaned out	2	14265	3/2/2022
	1025 Fieldstone Rd	Needs to be cleaned out	1	14277	3/3/2022
		pipe broken at invert - Make sure bottom of structure matches pipe invert elevation			

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'8.67246" - W83°26'42.26682"

Location: 1100 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'8.53689" - W83°26'42.71416"

Location: 1121 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'17.44497"-W83°26'43.93044"

Location: 1200 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'17.23167"-W83°26'44.13803"

Location: 1061 Creekshore Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'18.87133" - W83°26'44.07570"

Location: 1200 Creekshore Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'24.02018"-W83°26'47.87683"

Location: 1321 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# *Square Top*

## **CATCH BASIN INSPECTION CHECKLIST**

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N 33° 54' 24.43304" - W 83° 26' 48.02987"

Location: 1321B Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Spillway

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'23.1" W83°26'51.86795"

Location: 1341 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	<u>Need to be cleaned out</u>
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14265	Road Department	Michael Weathers		2/22/2022	7:30 AM

**Location of Request**

1341 Twin Lakes Rd

**Task**

Drainage problem

**Date Completed**

3/2/2022

**Action for Task**

cleaned 2 tons of debris out of flume

**Date of Action**

3/2/2022

**Employee Hours and Cost**
**# of Employees**
**Combined Hours**
**Cost of Action**

3

3.00

**Subcontractor Hours and Cost**

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	D147 NEW FLAT BED	1.00	
	D494 DUMP TRUCK	1.00	
	D878 CAT MINI EXCAVATOR	1.00	
	G489 FORD	1.00	

**Materials Cost**

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

**Total All Employee Costs:** \$0.00

**Total All Subcontractor Costs:** \$0.00

**Total All Equipment Costs:** \$0.00

**Total All Materials Costs:** \$0.00

**GRAND TOTAL:** \$0.00

# Spillway

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'18.55300" - W83°26'47.96601"

Location: 1228 Creekshore Dr. Watkinsville GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'17.40918" - W83°26'51.03704"

Location: 1110 Creekshore Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'16.88416" - W83°26'50.85503"

Location: 1120 Creekshore Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST***Square Top*Date: 2-22-2022Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°54'14.5" / W83°26'51.23547"Location: 1151 Creekshore Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Spillway

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'7.99503" - W83°26'44.91555"

Location: 1101 Birchmore Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Spillway

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'1.10914"-W83°26'47.19877"

Location: 1290 Creekshore Dr. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# 5quare Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'3.72074" - W83°26'41.41145"

Location: 1071 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'3.86245"-W83°26'41.18204"

Location: 1060 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'0.67638"-W83°26'39.59692"

Location: 1031 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## CATCH BASIN INSPECTION CHECKLIST

*Square Top*

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'0.64007"-W83°26'39.19698"

Location: 1020 Twin Lakes Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# *Square Top*

## **CATCH BASIN INSPECTION CHECKLIST**

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'8.41123" - W83°26'42.09073"

Location: 1041 Birchmore Dr. W. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# *Square Top*

## **CATCH BASIN INSPECTION CHECKLIST**

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'28.97286"-W83°26'47.40306"

Location: 1061 Springview Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'29.16486" - W83°26'47.08482

Location: 1040 Springview Ct. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'41.19792"-W83°28'41.03161"

Location: 1030 Fieldstone Rd. Waltherville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

SquatTop

**CATCH BASIN INSPECTION CHECKLIST**

Date: 2-22-2022

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°54'41.28733"-W83°28'41.22914"

Location: 1025 Fieldstone Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	<u>Need to be cleaned out</u>
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	<u>Pipe broken at invert</u>  <u>Make sure bottom of structure</u> <u>Matches pipe invert elevation.</u>

# Work Request Invoice - Public Works

WOID Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14277 Road Department	Michael Weathers		2/22/2022	7:30 AM

**Location of Request**

1025 Fieldstone Rd

**Task**

**Catch Basin Cleaning**

**Date Completed**

**3/3/2022**

**Action for Task**

removed 1 ton of silt from basin. Broken pipe i

**Date of Action**

**3/3/2022**

Employee Hours and Cost
# of Employees
Combined Hours
Cost of Action

4 4.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

D147 NEW FLAT BED	1.00
D494 DUMP TRUCK	1.00
D878 CAT MINI EXCAVATOR	1.00
G489 FORD	1.00

Materials Cost

**Employee Costs for this Task:** \$0.00

**Subcontractor Costs for this Task:** \$0.00

**Equipment Costs for this Task:** \$0.00

**Materials Costs for this Task:** \$0.00

**Total All Employee Costs:** \$0.00

**Total All Subcontractor Costs:** \$0.00

**Total All Equipment Costs:** \$0.00

**Total All Materials Costs:** \$0.00

**GRAND TOTAL:** \$0.00

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'42.84923"-W83°28'46.47200"

Location: 1085 Fieldstone Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Square Top

## CATCH BASIN INSPECTION CHECKLIST

Date: 2-22-2022

Inspector(s): William Rhodes

### Location/Description

GPS Point Name: N33°54'43.01665"-W83°28'46.93848"

Location: 1080 Fieldstone Rd. Watkinsville GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <u>No</u>	
"No dumping" educational marker	Yes / <u>No</u>	
Trash or debris at inlet opening	Yes / <u>No</u>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <u>No</u>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <u>No</u>	
Pipes (roots, damaged, flow impeded)	Yes / <u>No</u>	