



Inspection Date 12/8/22 Job Number GAO-253-128806

Job Name 1 HOP @ Epps Bridge

Job Address 1061 Parkway Place
Athens GA

Inspector's Name Tim Cooper

Grading Permit # _____ TCLP # _____

Lat: 33.92123 Long: 83.44237

Traffic ☐
Hatch ☒
Steel Lid ☐
Size 956 CST
Time 2 1/4
Disposal Fee (Y/N) Y
Volume (Gal.) 150

Maintenance Cleaning Checklist

Water Level	Oil Bucket Level	Sediment Level	Trash Conditions
☐ low	☐ low	☐ little	☐ minimal
☒ normal	☒ typical	☒ typical	☒ typical
☐ above outlet	☐ high	☒ excessive	☐ unacceptably high

Recommendations: This unit appears to need maintenance on a ☐ shorter ☐ longer ☒ unchanged schedule.

This report is a complete and accurate description of conditions found at the time of inspection and all work performed on this device

Inspector's Signature: Tim Cooper

Date: 12/8/22

Inspection Data

Sediment: inlet side	<u>16</u> Inches
Sediment: outlet side	<u>5</u> Inches

Water in unit at inspection	<u>46</u> Inches
Fluid in bucket at inspection	<u>35</u> Inches

Items Maintained

Comments

Lid: inspect bolts, eyehooks, hinges	<u>OK cleaned & maintained</u>
Trash Rack: inspect aluminum mesh	<u>OK cleaned</u>
Baffle Plates: inspect for damage	<u>OK #2 blown out. Wont stay in brackets</u>
Oil Bucket: Leaks / Sheen	<u>OK cleaned</u>
Surroundings: check grass/plantings	<u>OK</u>
Coconut Fiber / Flapper	<u>OK Replaced Coconut fiber</u>